



NJI3ECE

report date: 2024-03-29

General information

Make	FORD
Model	RANGER LIMITED 4X4 DCB TDCI
Colour	Black
Year of manufacture	2013
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-14
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-05
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	9

MOT #12	2023-12-02 12:05
MOT test number	474891000878
Result	✓ Passed
Next expiry date	2024-12-05
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #11	2022-12-03 13:05
MOT test number	977072371111
Result	✓ Passed

MOT #10	2021-12-06 12:30
MOT test number	275905773830
Result	✓ Passed

MOT #9	2021-12-02 14:58
MOT test number	807200853869
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #8** 2021-04-12 15:57**MOT test number** 242594196037**Result** ✓ Passed

- Advice** Exhaust corroded
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

MOT #7 2021-04-01 10:24**MOT test number** 467598713248**Result** ✗ Failed

- Advice** Items removed from driver's view prior to test
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Fail** Brake pipe leaking on a hydraulic braking system front to rear at front (1.1.11 (b) (ii))
- Fail** Brake pipe excessively corroded both front to rear at front (1.1.11 (c))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Exhaust corroded

MOT #6 2020-04-02 14:38**MOT test number** 987785786021**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #5** 2020-04-02 09:01**MOT test number** 647771473147**Result** ✗ Failed**Fail** Nearside Rear Leaf spring fractured (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Advice** Items removed from driver's view prior to test**MOT #4** 2019-03-25 16:44**MOT test number** 898775474430**Result** ✓ Passed**MOT #3** 2018-03-09 10:49**MOT test number** 315434548779**Result** ✓ Passed**Advice** Oil leak**MOT #2** 2017-03-01 16:35**MOT test number** 929307092258**Result** ✓ Passed**MOT #1** 2016-02-23 10:51**MOT test number** 492094195470**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
5 December 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-01
Last registration	2023-12-02
Complete history	See info



Registration #1	2013-03-01	8 mi
Registration #2	2016-02-23	46.465 mi
Registration #3	2017-03-01	65.577 mi
Registration #4	2018-03-09	75.908 mi
Registration #5	2019-03-25	83.254 mi
Registration #6	2020-04-02	101.104 mi
Registration #7	2020-04-02	101.104 mi
Registration #8	2020-04-02	101.104 mi
Registration #9	2020-04-02	101.104 mi
Registration #10	2020-04-02	101.104 mi
Registration #11	2020-04-02	101.104 mi
Registration #12	2020-04-02	101.104 mi
Registration #13	2020-04-02	101.104 mi
Registration #14	2020-04-02	101.104 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	86%
Pedestrian	81%
Safety systems	71%
Overall rating	89%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	CS79720