



Mercedes-Benz

MW08HWB

report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Silver
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	161 g/km
CO2 label	G







Internet history

Entry 2


Date	2021-10-23
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-05
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-21
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	34
Total items failed	11

MOT #15 2022-02-20 10:13

MOT test number 989227541898

Result ✓ Passed

Next expiry date 2023-02-21

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2021-02-02 14:39

MOT test number 203950857531

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Coil spring corroded (5.3.1 (b) (i))

Advice Fuel Pipe/s corroded

**MOT #13**

2021-02-02 11:05

MOT test number

593808435429

Result**✗ Failed****Advice** Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Front Registration plate insecure (0.1 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Fuel Pipe/s corroded**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #12**

2020-02-22 14:25

MOT test number

308989359800

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2020-02-07 12:15

MOT test number

827383764316

Result**✗ Failed**

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Front Bonnet primary retaining device ineffective (3.1 (c))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Off/side/front splash guard damaged
- Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Fuel Pipe/s corroded
- Fail** Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2019-02-07 10:44

MOT test number

238817939510

Result**✓ Passed**

**MOT #9** 2018-05-04 10:52**MOT test number** 585387109336**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Under shields fitted .**Advice** Items removed from driver's view prior to test**Advice** Offside Front tyre scuffed**MOT #8** 2017-05-09 11:03**MOT test number** 996347776491**Result** ✓ Passed**MOT #7** 2016-05-17 07:41**MOT test number** 730419725293**Result** ✓ Passed**MOT #6** 2015-06-25 09:46**MOT test number** 466556275163**Result** ✓ Passed**MOT #5** 2014-06-04 11:39**MOT test number** 448775654185**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Rear tyres split/perished

**MOT #4** 2013-06-03 08:22**MOT test number** 495934353173**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Under-trays fitted obscuring some underside components**Advice** Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #3** 2013-05-30 11:31**MOT test number** 515310053157**Result** ✗ Failed**Notice** Nail in offside rear tyre**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #2** 2012-06-21 10:25**MOT test number** 285653572124**Result** ✓ Passed**MOT #1** 2011-06-21 10:16**MOT test number** 626342771107**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 October 2022

X

MOT

Expired:
21 February 2023

Tax status	Expired at 1 October 2022
Days left	577 days too late
MOT expiry date	21 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-28
Last registration	2022-02-20
Complete history	See info



Registration #1	2008-06-28	13 mi
Registration #2	2011-06-21	16.193 mi
Registration #3	2012-06-21	18.941 mi
Registration #4	2013-05-30	21.412 mi
Registration #5	2013-06-03	21.457 mi
Registration #6	2014-06-04	23.685 mi
Registration #7	2015-06-25	26.165 mi
Registration #8	2016-05-17	28.850 mi
Registration #9	2017-05-09	34.730 mi
Registration #10	2018-05-20	35.377 mi
Registration #11	2019-05-20	35.377 mi
Registration #12	2019-05-20	35.377 mi
Registration #13	2019-05-20	35.377 mi
Registration #14	2019-05-20	35.377 mi
Registration #15	2019-05-20	35.377 mi
Registration #16	2019-05-20	35.377 mi
Registration #17	2019-05-20	35.377 mi
Registration #18	2019-05-20	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030487950