



report date: 2024-03-28

General information

Make	KIA
Model	SEDONA CRDI TS
Colour	Blue
Year of manufacture	2009
Top speed	122 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-08
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	52
Total items failed	9

MOT #20	2024-02-09 09:34
MOT test number	244421957619
Result	✓ Passed
Next expiry date	2025-02-08

MOT #19	2024-02-07 13:45
MOT test number	330249753954
Result	✗ Failed
MAJOR Windscreen washer not working (3.5 (a))	

MOT #18	2023-02-08 10:55
MOT test number	634020281169
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

**MOT #17**

2023-01-26 11:47

MOT test number

831033147956

Result**✗ Failed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR

Offside Rear Suspension arm pin or bush excessively worn Upper Center front (5.3.4 (a) (i))

Minor

Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #16

2022-01-20 12:21

MOT test number

238508870199

Result**✓ Passed****Advice**

Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bush (5.3.4 (a) (i))

Advice

Nearside Front Side repeater slightly discoloured (4.4.3 (a))

Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice

Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner bush (5.3.4 (a) (i))

Advice

Offside Front Side repeater slightly discoloured (4.4.3 (a))

Advice

Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #15**

2021-02-01 16:50

MOT test number

495532091765

Result

✓ Passed

Advice Front to rear underbody/all mechanical components covered in underseal**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Parking brake lever high**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #14**

2021-01-29 11:05

MOT test number

940569227930

Result

✗ Failed

MAJOR Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MAJOR** Front Position lamp not working (4.2.1 (a) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Parking brake lever high

**MOT #13** 2020-01-13 12:41**MOT test number** 839128320789**Result** ✓ Passed**MOT #12** 2020-01-11 13:36**MOT test number** 629888194861**Result** ✗ Failed**DA** **ANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DA** **ANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2019-01-15 10:18**MOT test number** 885242907379**Result** ✓ Passed**Advice** Rear Could not assess condition of rear pads due to caliper design both rear**Advice** Nearside Rear Handbrake effort just met and will need attention**MOT #10** 2019-01-15 10:18**MOT test number** 324565165207**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper blade missing Not missing but wiper was insecure (3.4 (b) (ii))**Advice** Nearside Rear Handbrake effort just met and will need attention**Advice** Rear Could not assess condition of rear pads due to caliper design both rear**MOT #9** 2018-02-26 09:49**MOT test number** 178120089844**Result** ✓ Passed

**MOT #8** 2017-02-18 12:17**MOT test number** 158619688280**Result** ✓ Passed

- Advice** Offside Front tyre has slight bind
- Advice** Handbrake has little reserve travel but RBT results satisfactory
- Advice** Rear could not assess condition of rear pads but seem low
- Advice** Offside Rear Tyre worn close to the legal limit on legal limit at time of test and will need replacing imminently (4.1.E.1)

MOT #7 2016-03-05 09:35**MOT test number** 594888703505**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin Both rear pads low (3.5.1g)

MOT #6 2015-03-11 17:02**MOT test number** 485200875090**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5**

2015-03-09 12:23

MOT test number

249468765030

Result**✗ Failed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Bonnet retaining device ineffective (8.4.2)**Fail** Offside Rear Wheel nut(s) missing (4.2.A.1e)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #4**

2014-02-26 12:59

MOT test number

115377154000

Result**✓ Passed****MOT #3**

2013-02-25 14:23

MOT test number

318036953053

Result**✓ Passed**



MOT #2	2012-02-29 14:33
MOT test number	355020562073
Result	✓ Passed
Notice	Nearside rear tyre worn on outer
Advice	Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #1	2012-02-29 14:33
MOT test number	856340962032
Result	✗ Failed
Advice	Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
Notice	Nearside rear tyre worn on outer
Pass with rectification	Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-11
Last registration	2024-02-09
Complete history	See info



Registration #1	2009-03-11	27 mi
Registration #2	2012-02-29	51.291 mi
Registration #3	2013-02-25	60.925 mi
Registration #4	2014-02-26	68.623 mi
Registration #5	2015-03-09	75.929 mi
Registration #6	2015-03-11	75.929 mi
Registration #7	2016-03-05	80.037 mi
Registration #8	2017-02-18	93.105 mi
Registration #9	2018-02-26	106.828 mi
Registration #10	2019-01-15	116.277 mi
Registration #11	2019-01-15	116.277 mi
Registration #12	2019-01-15	116.277 mi
Registration #13	2019-01-15	116.277 mi
Registration #14	2019-01-15	116.277 mi
Registration #15	2019-01-15	116.277 mi
Registration #16	2019-01-15	116.277 mi
Registration #17	2019-01-15	116.277 mi
Registration #18	2019-01-15	116.277 mi
Registration #19	2019-01-15	116.277 mi
Registration #20	2019-01-15	116.277 mi
Registration #21	2019-01-15	116.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2168 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3 8 305539