





report date: 2024-03-29

### General information

Make	MAZDA
Model	6 D TS2
Colour	White
Year of manufacture	2012
Top speed	132 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/12



## Internet history

### Entry 2

Date 2023-03-26

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-04-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	9
Total items failed	6

MOT #13	2024-04-16 09:19
MOT test number	127604661412
Result	✓ Passed
Next expiry date	2025-04-15

MOT #12	2023-04-05 09:30
MOT test number	187370804936
Result	<b>✓</b> Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front arm rear bushes (5.3.4 (a) (i))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/12



**MOT #11** 2023-04-03 10:38

**MOT test number** 719273257384

**Result** X Failed

**Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front arm rear bushes (5.3.4 (a) (i))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #10** 2022-04-06 15:48

**MOT test number** 342009678478

Result \rightarrow Passed

MOT #9 2022-04-06 08:28

**MOT test number** 801809211635

**Result** X Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened Both rears (1.1.14 (a) (ii))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #8** 2021-04-16 10:07

MOT test number 300023570220

**Result** ✓ Passed

MOT #7 2020-02-14 13:40

**MOT test number** 956367572442

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



MOT #6 2019-02-04 09:25

**MOT test number** 963736711160

MOT #5 2018-02-01 09:32

**MOT test number** 965585702775

**Result** 
✓ Passed

Advice Nearside Front Inner tyre at 3mm

MOT #4 2017-02-16 11:55

**MOT test number** 439490689589

**Result** ✓ Passed

MOT #3 2016-11-04 14:10

**MOT test number** 406991912531

**Result** ✓ Passed

MOT #2 2016-03-25 10:23

**MOT test number** 511911791421

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2015-02-26 11:56

MOT test number 168337855022

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	15 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



0	و من مطما ما
Owner	nistory

e when motorly	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
************	
manage of the same	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK NA
Fishs since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-05
Last registration	2024-04-16
Complete history	See info



Registration #1	2012-03-05	11 mi
Registration #2	2015-02-26	28.164 mi
Registration #3	2016-03-25	34.775 mi
Registration #4	2016-11-04	38.256 mi
Registration #5	2017-02-16	38.312 mi
Registration #6	2018-02-01	47.898 mi
Registration #7	2019-02-04	57.601 mi
Registration #8	2020-02-14	65.070 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 esi

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



# Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

## Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10300610

CarCheck.co.uk page 12/12