



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





## MOT history

**MOT expiry date** 2021-01-30**MOT pass rate** 79 %**MOT passed** 11**Failed MOT tests** 3**Total advice items** 10**Total items failed** 8**MOT #14** 2020-01-09 16:46**MOT test number** 453739673032**Result** Passed**Next expiry date** 2021-01-30**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2019-12-31 13:11**MOT test number** 150066050212**Result** Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Rear Suspension arm pin or bush excessively worn ROSE BUSH (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Suspension arm pin or bush excessively worn ROSE BUSH (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Position lamp not working sidelight (4.2.1 (a) (ii))

**MOT #12** 2019-01-09 10:40**MOT test number** 558234901702**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main run above subframe (1.1.11 (c))**Advice** Front Power steering component has slight seepage from a component at rack (2.1.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2018-01-18 10:38**MOT test number** 384407412755**Result** ✓ Passed**MOT #10** 2017-01-07 14:34**MOT test number** 361422697909**Result** ✓ Passed**MOT #9** 2016-01-23 10:10**MOT test number** 306593544421**Result** ✓ Passed**MOT #8** 2015-01-31 09:17**MOT test number** 999421935098**Result** ✓ Passed**MOT #7** 2014-01-11 10:05**MOT test number** 878701014031**Result** ✓ Passed

**MOT #6** 2013-01-09 14:40**MOT test number** 107619803492**Result** ✓ Passed**MOT #5** 2013-01-08 11:51**MOT test number** 455848603070**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #4** 2012-01-16 11:48**MOT test number** 435226912022**Result** ✓ Passed**MOT #3** 2012-01-14 09:32**MOT test number** 867874012049**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #2** 2011-01-31 16:03**MOT test number** 188521531035**Result** ✓ Passed**MOT #1** 2010-03-26 11:16**MOT test number** 681235780008**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
30 September 2020

✕  
MOT

Expired:  
30 January 2021

Tax status	Expired at 30 September
Days left	1308 days too late
MOT expiry date	30 January 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YH07KBF
Plate since	2019-06-29
Current registration	YH07KBF
Plate since	2019-06-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-04-11
Last registration	2020-01-09
Complete history	<a href="#">See info</a>



Registration #1	2007-04-11	13 mi
Registration #2	2010-03-26	37.356 mi
Registration #3	2011-01-31	45.541 mi
Registration #4	2012-01-14	47.389 mi
Registration #5	2012-01-16	47.389 mi
Registration #6	2013-01-08	49.249 mi
Registration #7	2013-01-09	49.249 mi
Registration #8	2014-01-11	51.578 mi
Registration #9	2015-01-11	53.907 mi
Registration #10	2015-01-11	53.907 mi
Registration #11	2015-01-11	53.907 mi
Registration #12	2015-01-11	53.907 mi
Registration #13	2015-01-11	53.907 mi
Registration #14	2015-01-11	53.907 mi
Registration #15	2015-01-11	53.907 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118