





report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 ES
Colour	White
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry	1

LIILI Y I	
Date	2022-02-11
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-22
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #9	2023-11-13 15:03
MOT test number	149666149679
Result	✓ Passed
Next expiry date	2024-11-22

MOT #8		2022-11-14 09:50
MOT test	number	495822179089
Result		✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #7	2021-11-22 09:01
MOT test number	769076040193
Result	✓ Passed

CarCheck.co.uk page 3/12



YS13GZV

report date: 2024-03-28

MOT test number

122725260836

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-11-23 11:13 **MOT** test number 921599852396 Result **X** Failed Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #4		2019-11-08 09:46
MOT test	number	763426813187
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/12



MOT #3 2018-11-13 15:32

MOT test number 696844830103

Result ✓ Passed

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2017-11-14 14:50

MOT test number 365961611844

Result

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2016-05-20 13:43

MOT test number 168715475587

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 22 November 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vahiala alaas	40
Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



YS13GZV

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



YS13GZV

report date: 2024-03-28

Owner	hictory
Owner	HISLOIN

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NIA.
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-20
Last registration	2023-11-13
Complete history	See info



Registration #1	2013-06-20	21 mi
Registration #2	2016-05-20	68.594 mi
Registration #3	2017-11-14	83.466 mi
Registration #4	2018-11-13	99.177 mi
Registration #5	2019-11-08	111.779 mi
Registration #6	2020-11-23	117.574 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1519 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12