





report date: 2024-03-28

#### General information

Make	CITROEN	
Model	C3 PICASSO PURETECH PLATINUM PICASSO	
Colour	Black	
Year of manufacture	2016	
Top speed	116 mph	
0 - 60 mph	11.8 seconds	
Gearbox	5 speed Manual	

### Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28


### Internet history

#### Entry 1

Date 2022-02-02

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT expiry date	2025-02-12
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	28
Total items failed	6

MOT #9		2024-02-13 13:26
MOT test	number	812683285528
Result		✓ Passed
Next expi	ry date	2025-02-12
Advice	Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Rear seats folded down Rear seat belts not fully inspected	
Advice	Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #8	2023-03-09 14:24
MOT test number	791638527639
Result	✓ Passed
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))  Advice Offside Rear Outer Tyre slightly damaged Side Wall (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number
910350226594

Result

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Outer Tyre slightly damaged Side Wall (5.2.3 (d) (ii))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT** #6 2022-03-28 15:45 **MOT** test number 686949435057 Result Passed **MOT #5** 2021-09-28 13:41 **MOT** test number 870914607055 Result Passed **Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f)) Advice Nearside front tyre and offside front tyre have numerous very small tears in tread faces **Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #4** 2021-09-28 13:41 **MOT** test number 409449035253 Result × Failed Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Nearside front tyre and offside front tyre have numerous very small tears in tread faces Advice Nearside Front Service brake binding but not excessively (1.2.1 (f)) Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/13




report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Flexi joint exhaust deteriated



CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2019-09-20 14:14

**MOT test number** 247696627706

Result ✓ Passed **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** 

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	12 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

_	
Owner	hictory
	11136011

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-26
Last registration	2024-02-13
Complete history	See info



Registration #1	2016-09-26	29 mi
Registration #2	2019-09-20	33.090 mi
Registration #3	2020-09-24	43.520 mi
Registration #4	2020-09-25	43.523 mi
Registration #5	2021-09-28	53.606 mi
Registration #6	2021-09-28	53.606 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Safety ratings

NCAP rating	***
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



## Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

### Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30396110

CarCheck.co.uk page 13/13