





report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO ML20 DCI
Colour	Blue
Year of manufacture	2012
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	58.8 mpg
Consumption combined	54.3 mpg



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-06-06

Pictures 2

Listing price <u>View report</u>





source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-05-24
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	7

MOT #11		2023-05-19 09:14
MOT test	number	387529960557
Result		✓ Passed
Next expi	ry date	2024-05-24
Advice	Offside Front Inner Oil leak, but not excessive driveshaft seal (8.4.1 (a) (i))	
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10		2022-05-25 15:30
MOT test	number	521887113190
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened n/s $\&$ 0	o/s (1.1.14 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/13



MOT #9 2021-01-22 14:16

MOT test number 419492652408

Result ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2021-01-22 10:16

MOT test number 872411678349

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #7 2020-02-05 16:58

MOT test number 915697397336

Result
✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s inner face (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



MOT #6 2018-02-02 10:44

MOT test number 487927746129

Result ✓ Passed

Advice O/s edge of windscreen has small crack, but not in drivers view

MOT #5 2018-02-01 13:09

MOT test number 960677255834

Result × Failed

Advice O/s/f tyre badly worn on inner edge through to another layer of rubber

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice O/s edge of windscreen has small crack, but not in drivers view

Fail Offside Rear Stop lamp not working (1.2.1b)

MOT #4 2017-03-09 09:32

MOT test number 853450500682

MOT #3 2017-03-08 10:13

MOT test number 856881073297

Result X Failed

Fail Parking brake lever has no reserve travel (3.1.6b)

MOT #2 2016-03-11 07:13

MOT test number 684503158455

Result
✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/13



MOT #1

MOT test number

599874965095

Result

Notice Rear indicators starting to go pale

CarCheck.co.uk page 6/13



24 May 2024

See MOT history

Tax & MOT check

MOT expiry date

Full MOT history



CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



\sim	
Owner	nictory
OWILL	IIISLUIV
~	,

•	
For how long did the current and previous owner(s) have this RENAULT? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	OK SIE
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-30
Last registration	2023-05-19
Complete history	See info



Registration #1	2012-03-30	23 mi
Registration #2	2015-03-05	20.838 mi
Registration #3	2016-03-11	27.728 mi
Registration #4	2017-03-08	34.565 mi
Registration #5	2017-03-09	34.566 mi
Registration #6	2018-02-01	51.964 mi
Registration #7	2018-02-02	51.964 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1844 mm
Length	4213 mm
Kerb weight	1277 kg
Max. allowed weight	2095 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D044926

CarCheck.co.uk page 13/13