



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 8V ACTIVE
Colour	Blue
Year of manufacture	2009
Top speed	90 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.2 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-17
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-02
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	8
Total items failed	12

MOT #14 2023-08-29 09:04

MOT test number 830752615144

Result ✓ Passed

Next expiry date 2024-08-31

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #13 2022-09-01 15:11

MOT test number 479479932622

Result ✓ Passed

MOT #12 2021-08-20 12:08

MOT test number 266663081990

Result ✓ Passed

**MOT #11** 2021-08-20 08:12**MOT test number** 270349006159**Result** ✗ Failed**Fail** Front Tyre has ply or cords exposed both (5.2.3 (d) (ii))**Fail** Front Tyre tread depth below requirements of 1.6mm both. 185/65r15h (5.2.3 (e))**MOT #10** 2019-07-09 16:08**MOT test number** 105569287977**Result** ✓ Passed**MOT #9** 2019-07-08 15:13**MOT test number** 981300484533**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Front Suspension arm pin or bush excessively worn Both (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2018-07-04 15:44**MOT test number** 682075378244**Result** ✓ Passed**MOT #7** 2017-07-25 08:54**MOT test number** 982699540011**Result** ✓ Passed

**MOT #6** 2017-07-25 08:53**MOT test number** 815458197796**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Stop lamp not working (1.2.1b)

MOT #5 2016-07-13 08:44**MOT test number** 656799338178**Result** ✓ Passed**MOT #4** 2016-07-13 08:44**MOT test number** 899068295668**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

MOT #3 2015-07-07 11:52**MOT test number** 926788185196**Result** ✓ Passed



MOT #22015-07-06 16:27

MOT test number448387685166

Result

Failed

NoticeBoth rear tyres perished

FailNearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

AdviceNearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

NoticeSpare missing

FailFront Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #12013-06-05 16:44

MOT test number269566153128

Result

Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	RE59OLK
Plate since	2024-03-29
Current registration	RE59OLK
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-27
Last registration	2023-08-29
Complete history	See info



Registration #1	2009-11-27	25 mi
Registration #2	2013-06-05	23.903 mi
Registration #3	2015-07-06	33.905 mi
Registration #4	2015-07-07	33.905 mi
Registration #5	2016-07-13	48.740 mi
Registration #6	2016-07-13	48.740 mi
Registration #7	2017-07-25	62.677 mi
Registration #8	2017-07-25	62.677 mi
Registration #9	2018-07-04	80.695 mi
Registration #10	2019-06-20	95.377 mi
Registration #11	2019-06-20	95.377 mi
Registration #12	2019-06-20	95.377 mi
Registration #13	2019-06-20	95.377 mi
Registration #14	2019-06-20	95.377 mi
Registration #15	2019-06-20	95.377 mi
Registration #16	2019-06-20	95.377 mi
Registration #17	2019-06-20	95.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

5055820