





## General information

Make	ΤΟΥΟΤΑ
Model	RAV-4 D-4D T180
Colour	Black
Year of manufacture	2006
Top speed	124 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	174 BHP	0 < 101 A
Max. torque	400 Nm at 2.000 rpm	101 - 120 <sup>B</sup>
Engine capacity	2.231 сс	121 - 140 P
Cylinders	4	141 - 165 <sup>F</sup> <sub>G</sub>
Fuel type	Diesel	166 - 185 H LABEL I
Consumption city	33.2 mpg	186 - 225 J
Consumption extra urban	46.3 mpg	225+ L M
Consumption combined	40.4 mpg	
CO2 emission	185 g/km	
CO2 label	I	





# Internet history

Entry	1

Date Pictures 2021-06-28

12

Listing price

View report









source: cargurus.co.uk



# MOT history

MOT expiry date	2025-04-18
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	28
Total items failed	1

MOT #18		2024-04-15 14:48
MOT test number		314473301873
Result		✓ Passed
Next expiry date		2025-04-18
Advice Offside	Front Play in steering rack inner joint(s)	
Advice Knockir	ng from steering wheel when rocking side to side. No visible play i	n components that can
Advice Nearsic	de Front Play in steering rack inner joint(s)	
Advice Exhaus	st has a minor leak of exhaust gases Top side of middle box (6.1.2	(a))

MOT #17		2024-04-12 09:19
MOT test i	number	169533500275
Result		🗙 Failed
Advice	Offside Front Play in steering rack inner joint(s)	
<b>MAJOR</b> (1.1.6 (c))	Parking brake lever has excessive movement indicating incorrect adjustment No	o reserve travel
<b>MAJOR</b> (5.2.3 (d) (	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reac i))	ch the ply or cords
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Exhaust has a minor leak of exhaust gases Top side of middle box $(6.1.2 (a))$	
Advice be seen.	Knocking from steering wheel when rocking side to side. No visible play in comp	onents that can





MOT #16	2023-04-06 09:57
MOT test number	814130327719
Result	✓ Passed
Advice Nearside Front Headlamp has a product (b))	t on the lens but not seriously reducing light output (4.1.4
Advice Offside Front Headlamp has a product (b))	on the lens but not seriously reducing light output (4.1.4

MOT #15	2022-04-19 07:44
MOT test number	451583804071
Result	✓ Passed
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Nail in tyre	

MOT #14	2021-03-19 16:07
MOT test number	805592814303
Result	✓ Passed

MOT #13	2020-01-06 15:41
MOT test number	576093206569
Result	✓ Passed

MOT #12		2020-01-06 13:27
MOT test	number	300700650247
Result		🗙 Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Offside Rear Seat belt not functioning as intended (7.1.2 (c))	





MOT #11	2018-12-04 15:32
MOT test number	309415993100
Result	✓ Passed
MOT #10	2017-12-04 16:31
MOT test number	301429130199
Result	✓ Passed
Advice Nearside Rear Outer wall cracking up	
Advice Nearside Front Lower Suspension arm ball joint dust cover damaged,	, but preventing the ingress of
dirt (2.4.G.2)	
Advice Offside Front tyre outer walldamaged	
Advice Offside Rear Outer wall cracking up	

МОТ #9	2016-12-01 12:49
MOT test number	529948409813
Result	✓ Passed

MOT #8	2015-12-04 09:37
MOT test number	104671345638
Result	✓ Passed

MOT #7	2014-12-19 17:57
MOT test number	397253954371
Result	✓ Passed

МОТ #6	2014-01-07 10:10
MOT test number	365177904022
Result	✓ Passed





MOT #5	2012-10-10 14:44
MOT test number	367874982284
Result	Passed
AdviceFront brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)AdviceFront Brake pad(s) wearing thin (3.5.1g)	

MOT #4	2011-10-03 13:40
MOT test number	317696271206
Result	✓ Passed
<b>Notice</b> Both front tyre sidewalls perished.	
Advice Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2011-10-03 13:40
MOT test number	985646871246
Result	× Failed
<b>Notice</b> Both front tyre s	idewalls perished.
Advice Front Tyre worn	close to the legal limit (4.1.E.1)
<b>Pass with rectification</b> by more than 40mm outside	Windscreen has a sticker or other obstruction encroaching into the swept area zone 'A' (8.3.1e)

MOT #2	2010-10-18 12:39
MOT test number	334521690238
Result	✓ Passed
MOT #1	2009-10-13 17:30

MOT test number	353606589416
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 July 2024	✓ MOT Expires: 18 April 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



FG56MXB report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-25
Last registration	2024-04-15
Complete history	See info



Registration #1	2006-10-25	21 mi
Registration #2	2009-10-13	24.998 mi
Registration #3	2010-10-18	34.108 mi
Registration #4	2011-10-03	43.907 mi
Registration #5	2012-10-10	52.374 mi
Registration #6	2014-01-07	55.687 mi
Registration #7	2014-12-19	58.738 mi
Registration #8	2015-12-04	63.293 mi
Registration #9	2016-12-01	66.109 mi
Registration #10	2017-12-04	69.054 mi
•		
Registration #11		11.777 es
-		10.000 est
Registration #11		00.000 est 01.000 est 00.000 est
Registration #11 Registration #12		00.000 est 01.000 est 00.000 est 01.000 est
Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est
Registration #11 Registration #12 Registration #13 Registration #14		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est 00.000 est
Registration #11Registration #12Registration #13Registration #14Registration #15		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		10.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1595 kg
Max. allowed weight	2190 kg
Additional information	
Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	2AD0064421