



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Black
Year of manufacture	2007
Top speed	154 mph
0 - 60 mph	7.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.9 mpg
Consumption extra urban	39.2 mpg
Consumption combined	29.7 mpg
CO2 emission	227 g/km
CO2 label	L







Internet history

Entry 1

Date	2021-12-09
Pictures	43
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-19
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	30
Total items failed	9

MOT #212023-12-18 13:21

MOT test number682039566106

Result✓ Passed

Next expiry date2024-12-19

- Advice**Undershields fitted not allowing full inspection of vehicle.
- Advice**Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice**Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm, inner bush (5.3.4 (a) (i))
- Advice**Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice**Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm, inner bush (5.3.4 (a) (i))

**MOT #20**

2023-12-15 15:41

MOT test number

579702224952

Result

✗ Failed

- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Undershields fitted not allowing full inspection of vehicle.
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm, inner bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm, inner bush (5.3.4 (a) (i))

MOT #19

2022-12-10 09:56

MOT test number

751549868489

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Undershields fitted not allowing full inspection of vehicle.

**MOT #18**

2022-12-08 11:41

MOT test number

955188678861

Result

✗ Failed

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Undershields fitted not allowing full inspection of vehicle.

Advice

Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #17

2021-12-20 13:09

MOT test number

366665445876

Result

✓ Passed

MOT #16

2021-12-20 13:09

MOT test number

556270855755

Result

✗ Failed

Pass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15

2021-03-19 07:34

MOT test number

713367002395

Result

✓ Passed



MOT #14	2020-06-15 08:56
MOT test number	810500446787
Result	✓ Passed
MOT #13	2019-06-18 08:47
MOT test number	688007591820
Result	✓ Passed
MOT #12	2018-06-15 15:12
MOT test number	265488349605
Result	✓ Passed
MOT #11	2018-06-14 08:49
MOT test number	806799286746
Result	✗ Failed
<div><div>Fail</div> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))</div> <div><div>Fail</div> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))</div>	
MOT #10	2017-06-27 09:02
MOT test number	461777102887
Result	✓ Passed
MOT #9	2017-06-26 15:26
MOT test number	492885887663
Result	✗ Failed
<div><div>Fail</div> Offside Front Outer Suspension arm has excessive play in a ball joint rear (2.4.G.2)</div>	
MOT #8	2016-05-26 08:22
MOT test number	399304423142
Result	✓ Passed



MOT #7	2015-05-21 14:56
---------------	------------------

MOT test number	949501045120
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2015-05-21 14:56
---------------	------------------

MOT test number	669381545133
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
--------------------------------	--

MOT #5	2014-06-03 10:53
---------------	------------------

MOT test number	596794654122
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-06-03 10:35
---------------	------------------

MOT test number	277514153119
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-05-28 09:40
---------------	------------------

MOT test number	699639342168
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-06-06 09:47
---------------	------------------

MOT test number	696357951188
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-06-08 16:56
---------------	------------------

MOT test number	772939950108
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
19 December 2024

Tax status		Valid until 1 December
Days left		215
MOT expiry date		19 December 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-01
Last registration	2023-12-18
Complete history	See info



Registration #1	2007-09-01	29 mi
Registration #2	2010-06-08	20.834 mi
Registration #3	2011-06-06	26.193 mi
Registration #4	2012-05-28	30.860 mi
Registration #5	2013-06-03	35.411 mi
Registration #6	2014-06-03	38.640 mi
Registration #7	2015-05-21	42.157 mi
Registration #8	2016-05-26	46.824 mi
Registration #9	2017-06-26	50.849 mi
Registration #10	2017-06-27	50.866 mi
Registration #11	2018-06-14	55.884 mi
Registration #12	2019-06-20	59.277 mi
Registration #13	2020-06-20	62.277 mi
Registration #14	2021-06-20	65.277 mi
Registration #15	2022-06-20	68.277 mi
Registration #16	2023-06-20	71.277 mi
Registration #17	2023-06-20	74.277 mi
Registration #18	2023-06-20	77.277 mi
Registration #19	2023-06-20	80.277 mi
Registration #20	2023-06-20	83.277 mi
Registration #21	2023-06-20	86.277 mi
Registration #22	2023-06-20	89.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1580 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030689259