



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 3


Date	2022-02-27
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-10-03
Pictures	18
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-03
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-30
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	23
Total items failed	17

MOT #162023-10-30 13:48

MOT test number281921688146

Result✓ Passed

Next expiry date2024-10-30

- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
- AdviceNearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceRear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2023-10-30 09:02

MOT test number

465368088046

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14

2022-10-31 14:56

MOT test number

586700317627

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Headlight leveler o/s/f insecure and possibly not working
- Minor** Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13**

2022-10-31 12:05

MOT test number

903236517680

Result

✗ Failed

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))**Minor** Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Headlight leveler o/s/f insecure and possibly not working**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #12**

2021-10-21 10:25

MOT test number

817263188897

Result

✓ Passed

Advice Parking brake lever worn, but not excessively (1.1.6 (b) (i))**MOT #11**

2020-10-28 11:21

MOT test number

511676860381

Result

✓ Passed

MOT #10

2020-10-27 12:35

MOT test number

239899018973

Result

✗ Failed

Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9** 2019-10-14 11:24**MOT test number** 966349077328**Result** ✓ Passed**MOT #8** 2018-10-23 09:48**MOT test number** 424667711073**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2018-10-23 09:48**MOT test number** 898185623332**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2017-10-13 11:34**MOT test number** 273321369163**Result** ✓ Passed

**MOT #5** 2017-10-13 08:12**MOT test number** 542553230902**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #4** 2016-06-13 08:20**MOT test number** 955652406961**Result** ✓ Passed**MOT #3** 2016-06-13 08:20**MOT test number** 127977261370**Result** ✗ Failed**Pass with rectification** Offside Steering rack gaiter insecure (2.2.D.2d)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Steering rack gaiter insecure (2.2.D.2d)**MOT #2** 2015-03-11 14:37**MOT test number** 108840475489**Result** ✓ Passed**MOT #1** 2014-04-09 11:06**MOT test number** 696369994049**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
30 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-04-19
Last registration	2023-10-30
Complete history	See info



Registration #1	2011-04-19	19 mi
Registration #2	2014-04-09	19.162 mi
Registration #3	2015-03-11	23.274 mi
Registration #4	2016-06-13	33.837 mi
Registration #5	2016-06-13	33.837 mi
Registration #6	2017-10-13	43.540 mi
Registration #7	2017-10-13	43.540 mi
Registration #8	2018-10-23	52.362 mi
Registration #9	2018-10-23	52.362 mi
Registration #10	2019-10-14	60.702 mi
Registration #11	2019-10-14	60.702 mi
Registration #12	2019-10-14	60.702 mi
Registration #13	2019-10-14	60.702 mi
Registration #14	2019-10-14	60.702 mi
Registration #15	2019-10-14	60.702 mi
Registration #16	2019-10-14	60.702 mi
Registration #17	2019-10-14	60.702 mi
Registration #18	2019-10-14	60.702 mi
Registration #19	2019-10-14	60.702 mi
Registration #20	2019-10-14	60.702 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------