





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Grey
Year of manufacture	2014
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-08-07

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



469262356746

MOT history

MOT test number

MOT expiry date	2025-03-26
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	1

MOT #10	2024-02-29 14:32
MOT test number	968471866773
Result	✓ Passed
Next expiry date	2025-03-26
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #9	2023-03-27 16:41
MOT test number	687404967117
Result	✓ Passed

1101 #6	2022 07 22 14.20
MOT test number	729995447466
Result	√ Passed

MOT #7	2022-07-22 10:12

Result × Failed

MAJOR Offside Rear Parking brake inoperative on one side (1.4.1 (a))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

CarCheck.co.uk page 3/11



(b) (ii))

AF64XZL report date: 2024-03-29

MOT #6 2022-01-11 17:20

MOT test number 744052978273

MOT #5 2020-10-14 15:05

MOT test number 387272044371

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2019-10-07 15:17

MOT test number 344635405877

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-10-18 16:21

MOT test number 613288193924

Result

Passed

MOT #2 2018-10-18 16:21

MOT test number 754115780932

Result X Failed

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #1 2017-09-12 09:58

MOT test number 750588200630

Result
✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



AF64XZL

report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



AF64XZL

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2024-02-29
Complete history	See info



2014-09-30	13 mi
2017-09-12	14.780 mi
2018-10-18	25.159 mi
2018-10-18	25.159 mi
2019-10-07	36.098 mi
2020-10-14	42.254 mi
	11.777 es
	2017-09-12 2018-10-18 2018-10-18 2019-10-07

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1294 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number G4FCEZ336660