





report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	White
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-03-11

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



WK64UKA report date: 2024-03-28

MOT history

MOT expiry date	2025-03-15
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	11
Total items failed	7

MOT #12	2024-03-01 15:14
MOT test number	481482108307
Result	✓ Passed
Next expiry date	2025-03-15
Advice Nearside front daytime running not working	
Advice Nearside rear parking brake weak	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #11	2023-03-13 13:12
MOT test number	966194479502
Result	✓ Passed
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	

MOT #10	2022-03-16 11:08
MOT test number	718664965363
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2022-03-15 14:08

MOT test number 611463507111

Result X Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #8 2021-08-06 14:58

MOT test number 441588244808

Result ✓ Passed

MOT #7 2021-08-06 13:46

MOT test number 730086732879

Result X Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm worn low on edges (5.2.3 (e))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2020-07-30 10:13

MOT test number 492877067563

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2020-07-30 09:10

MOT test number 260411505396

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))

MOT #4 2019-08-01 12:56

MOT test number 141712626743

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2018-08-07 14:31

MOT test number 460534194174

MOT #2 2017-08-08 08:28

MOT test number 920014940652

Result

Passed

MOT #1 2017-08-08 08:28

MOT test number 262295610300

Result × Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

WK64UKA

report date: 2024-03-28

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-30
Last registration	2024-03-01
Complete history	See info



Registration #1	2014-09-30	6 mi
Registration #2	2017-08-08	8.546 mi
Registration #3	2017-08-08	8.546 mi
Registration #4	2018-08-07	12.667 mi
Registration #5	2019-08-01	17.405 mi
Registration #6	2020-07-30	25.327 mi
Registration #7	2020-07-30	25.327 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



WK64UKA report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	L2/12

Number of axles 2

Engine number 0798077