





report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 R-DESIGN NAV AWD
Colour	Grey
Year of manufacture	2013
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.5 mpg
CO2 emission	215 g/km
CO2 label	K



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-03
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	6
Total items failed	0

MOT #8	2023-10-25 15:41
MOT test number	812790468364
Result	✓ Passed
Next expiry date	2024-11-03

MOT #7		2022-10-26 09:04
MOT test	number	526987746811
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Offside Front Nail in tyre	

MOT #6	2021-11-03 16:14
MOT test number	453259541873
Result	✓ Passed

MOT #5		2020-11-04 15:47
MOT test	number	964576418877
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



MOT #4 2019-07-18 12:07

MOT test number 128879920262

MOT #3 2018-07-18 09:30

MOT test number 937168909859

Result ✓ Passed

MOT #2 2017-06-30 14:13

MOT test number 395212413107

Result ✓ Passed

MOT #1 2016-06-27 09:04

MOT test number 455431705046

Advice Emission too clean

Advice Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)

	More info	>
Plate changes See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-07-25
Last registration	2023-10-25
Complete history	See info



Registration #1	2013-07-25	11 mi
Registration #2	2016-06-27	35.275 mi
Registration #3	2017-06-30	46.592 mi
Registration #4	2018-07-18	60.027 mi
Registration #5	2019-07-18	70.299 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
B 1 1 11 1/0		
Registration #9		

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2112 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2172 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles2Engine number1316211