



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTi
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-01-08
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-19
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	22
Total items failed	1

MOT #9	2024-01-09 15:14
MOT test number	921974971340
Result	✓ Passed
Next expiry date	2025-01-19
Advice	Nearside Front Brake pipe corroded, covered in grease or other material to rear x2 covered in grease (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Coil spring corroded both coils (5.3.1 (b) (i))

MOT #8	2024-01-09 13:55
MOT test number	511171814759
Result	✗ Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
MAJOR	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Advice	Rear Coil spring corroded both coils (5.3.1 (b) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material to rear x2 covered in grease (1.1.11 (c))

**MOT #7**

2023-01-19 14:37

**MOT test number**

553783786510

**Result**

✓ Passed

- Advice** Rear Coil spring corroded both coils (5.3.1 (b) (i))
- Advice** Both front strut top upper mounting bearings slightly rough on operation
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material all brake pipes covered in grease (1.1.11 (c))

**MOT #6**

2023-01-17 11:00

**MOT test number**

641917071295

**Result**

✗ Failed

- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Rear Coil spring corroded both coils (5.3.1 (b) (i))
- MAJOR** Exhaust fumes entering cabin (6.1.2 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material all brake pipes covered in grease (1.1.11 (c))
- Advice** Both front strut top upper mounting bearings slightly rough on operation
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm 185/65/r15 92t (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #5**

2022-01-20 16:08

**MOT test number**

856281133229

**Result**

✓ Passed

- Minor** Offside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #4** 2022-01-20 16:08**MOT test number** 491765352152**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2021-03-17 14:53**MOT test number** 785156760913**Result** ✓ Passed**Minor** Offside Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #2** 2020-03-16 14:48**MOT test number** 830406355428**Result** ✓ Passed**MOT #1** 2019-03-18 14:51**MOT test number** 707974841382**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front and tracking off on inside shoulders (5.2.3 (e))



Tax & MOT check

✓

Taxed

Tax due:  
1 February 2025

✓

MOT

Expires:  
19 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	19 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-23
Last registration	2024-01-09
Complete history	<a href="#">See info</a>



Registration #1	2016-03-23	19 mi
Registration #2	2019-03-18	24.943 mi
Registration #3	2020-03-16	34.174 mi
Registration #4	2021-03-17	43.356 mi
Registration #5	2022-01-20	50.808 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A2000-5824911