




report date: 2024-03-29

General information

Make	NISSAN
Model	350 Z V6
Colour	Blue
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.1 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-10-17
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-03
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	28
Total items failed	23

MOT #24	2024-04-04 09:32
MOT test number	992508234873
Result	✓ Passed
Next expiry date	2025-04-03
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))

MOT #23	2023-04-04 10:38
MOT test number	711786054445
Result	✓ Passed
Advice	Light corrosion to front & rear suspension components & brake pipes

MOT #22	2022-03-09 09:38
MOT test number	478317997672
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face. (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face. (1.1.14 (a) (ii))

**MOT #21**

2022-03-09 09:38

MOT test number

960240755987

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face. (1.1.14 (a) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face. (1.1.14 (a) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #20**

2021-03-12 18:45

MOT test number

424247697496

Result**✓ Passed****Advice** Front cross member corroded not considered excessive**MOT #19**

2021-03-12 18:45

MOT test number

781173299122

Result**✗ Failed****Advice** Front cross member corroded not considered excessive**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #18**

2020-03-25 13:56

MOT test number

843882008801

Result**✓ Passed**

**MOT #17**

2020-03-25 13:56

MOT test number

763037117573

Result**✗ Failed**

- Pass with rectification** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Pass with rectification** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #16

2020-03-16 15:12

MOT test number

847890896739

Result**✗ Failed**

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #15

2019-03-19 17:01

MOT test number

312790639611

Result**✓ Passed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower ball joint dust cover cracking

**MOT #14** 2019-03-09 12:27**MOT test number** 339909835610**Result** ✗ Failed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases CENTER BOX WEAK/CORRODED (6.1.2 (a))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated CRACKING ON BOOT (5.3.4 (b) (i))**Advice** Nearside Front TYRE BALD AND CLOSE TO CORDS ON INNER TREAD,ADVISE REPLACEMENT**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Inner Tyre has ply or cords exposed Tyre bald on inner tread (5.2.3 (d) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated CRACKING ON BOOT (5.3.4 (b) (i))**MOT #13** 2018-02-16 13:24**MOT test number** 588987233001**Result** ✓ Passed**MOT #12** 2017-03-09 15:14**MOT test number** 291997977389**Result** ✓ Passed

**MOT #11** 2017-03-02 12:36**MOT test number** 949082555436**Result** ✗ Failed**Fail** Nearside Front Exhaust has a major leak of exhaust gases flexie (7.1.2)**Fail** Emissions not tested (7.3.A.1)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Exhaust has a major leak of exhaust gases centre box pipe (7.1.2)**MOT #10** 2016-03-14 17:34**MOT test number** 906216428752**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-03-07 15:47**MOT test number** 246391713738**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Tyre tread depth below requirements of 1.6mm both (4.1.E.1)**MOT #8** 2015-04-24 11:45**MOT test number** 899794015149**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-04-25 11:48**MOT test number** 439695714103**Result** ✓ Passed**MOT #6** 2013-04-26 11:56**MOT test number** 387516913115**Result** ✓ Passed**MOT #5** 2012-04-26 17:24**MOT test number** 356617712189**Result** ✓ Passed**MOT #4** 2011-03-01 13:17**MOT test number** 569570561057**Result** ✓ Passed**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-03-01 09:40**MOT test number** 525660461061**Result** ✗ Failed**Fail** Front Brake lining(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-03-18 08:09**MOT test number** 600237070090**Result** ✓ Passed**MOT #1** 2009-03-24 15:41**MOT test number** 932103589002**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
3 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-06-22
Last registration	2024-04-04
Complete history	See info



Registration #1	2005-06-22	26 mi
Registration #2	2009-03-24	19.608 mi
Registration #3	2010-03-18	28.348 mi
Registration #4	2011-03-01	36.934 mi
Registration #5	2011-03-01	36.934 mi
Registration #6	2012-04-26	43.364 mi
Registration #7	2013-04-26	46.299 mi
Registration #8	2014-04-25	50.356 mi
Registration #9	2015-04-24	53.150 mi
Registration #10	2016-03-07	53.819 mi
Registration #11	2016-03-14	53.823 mi
Registration #12	2017-03-02	56.259 mi
Registration #13	2017-03-09	56.274 mi
Registration #14	2018-03-09	56.274 mi
Registration #15	2018-03-09	56.274 mi
Registration #16	2018-03-09	56.274 mi
Registration #17	2018-03-09	56.274 mi
Registration #18	2018-03-09	56.274 mi
Registration #19	2018-03-09	56.274 mi
Registration #20	2018-03-09	56.274 mi
Registration #21	2018-03-09	56.274 mi
Registration #22	2018-03-09	56.274 mi
Registration #23	2018-03-09	56.274 mi
Registration #24	2018-03-09	56.274 mi
Registration #25	2018-03-09	56.274 mi
Registration #26	2018-03-09	56.274 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1330 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1644 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	418568