




report date: 2024-03-29

General information

Make	VOLVO
Model	C70 T
Colour	Silver
Year of manufacture	2003
Top speed	124 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	230 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	18.1 mpg
Consumption extra urban	36.7 mpg
Consumption combined	26.6 mpg
CO2 emission	253 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-02-06
Pictures	3
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2021-01-30
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	24
Total items failed	7

MOT #15 2019-07-31 10:01

MOT test number 769406929196

Result ✓ Passed

Next expiry date 2021-01-30

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2016-11-26 11:08

MOT test number 900407026512

Result ✓ Passed

Advice Offside Front Play in steering rack inner joint(s)

Advice Rear Direction indicator slightly discoloured N/S and O/S (1.4.A.2f)

Advice Offside Rear light lens is broken

MOT #13 2015-11-20 15:58

MOT test number 803842933833

Result ✓ Passed

Advice Front tyres worn on inside edges, Poss tracking out.

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e)

**MOT #12**

2015-11-19 14:41

MOT test number

494590576531

Result**✗ Failed**

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Front tyres worn on inside edges, Poss tracking out.

Advice Offside Rear Direction Indicator damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #11

2014-11-27 12:14

MOT test number

927271134374

Result**✓ Passed**

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2014-11-26 09:59**MOT test number** 158890034394**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Battery insecure (1.9.1)**MOT #9** 2013-09-23 17:20**MOT test number** 347466263492**Result** ✓ Passed**MOT #8** 2012-09-27 14:07**MOT test number** 197501372276**Result** ✓ Passed**MOT #7** 2011-05-26 10:18**MOT test number** 295246541462**Result** ✓ Passed**MOT #6** 2010-06-16 14:18**MOT test number** 284777360464**Result** ✗ Failed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)

**MOT #5** 2010-06-16 14:18**MOT test number** 272747860106**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-06-19 15:24**MOT test number** 901430079153**Result** ✓ Passed**MOT #3** 2008-05-29 12:22**MOT test number** 122270458182**Result** ✓ Passed**Notice** Power steering reservoir bottom hose damp**MOT #2** 2007-05-14 11:06**MOT test number** 814504337180**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2006-05-16 12:04**MOT test number** 460946936131**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 June 2018

✕
MOT

Expired:
30 January 2021

Tax status	Expired at 1 June 2018
Days left	2160 days too late
MOT expiry date	30 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2003-01-01
Last registration	2019-07-31
Complete history	See info



Registration #1	2003-01-01	7 mi
Registration #2	2006-05-16	24.553 mi
Registration #3	2007-05-14	33.483 mi
Registration #4	2008-05-29	41.538 mi
Registration #5	2009-06-19	47.296 mi
Registration #6	2010-06-16	53.141 mi
Registration #7	2011-05-26	55.985 mi
Registration #8	2012-09-27	60.324 mi
Registration #9	2013-05-29	65.377 mi
Registration #10	2014-05-29	70.377 mi
Registration #11	2015-05-29	75.377 mi
Registration #12	2016-05-29	80.377 mi
Registration #13	2017-05-29	85.377 mi
Registration #14	2018-05-29	90.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2020-05-29	100.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	2660 mm
Length	4720 mm
Wheel base	1420 mm
Kerb weight	1565 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	3085544