



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRTD GSI
Colour	Grey
Year of manufacture	2007
Top speed	110 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	155 BHP
Max. torque	335 Nm at 2.500 rpm
Engine capacity	2.188 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg
CO2 emission	218 g/km
CO2 label	K





MOT history

MOT expiry date	2021-06-08
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	25
Total items failed	15

MOT #17	2020-05-14 14:18
MOT test number	549155075692
Result	✓ Passed
Next expiry date	2021-06-08
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16	2019-05-09 12:02
MOT test number	866688629144
Result	✓ Passed

MOT #15	2019-05-09 10:09
MOT test number	148868583500
Result	✗ Failed
Fail	Front All position lamps not working (4.2.1 (a))
Fail	Rear Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Brake performance not tested (1.2.1 (g))
Fail	Front Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #14**

2018-05-09 12:42

MOT test number

627603709620

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**Advice** Air bag light is on**Advice** Brake lining(s) wearing thin all four (3.5.1g)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #13**

2018-05-09 10:19

MOT test number

392709464963

Result

✗ Failed

Fail Offside Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Brake lining(s) wearing thin all four (3.5.1g)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Fail** Nearside Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Air bag light is on**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**MOT #12**

2017-05-16 11:12

MOT test number

976034818431

Result

✓ Passed

**MOT #11** 2017-05-16 09:51**MOT test number** 541563412726**Result** ✗ Failed**Pass with rectification** Front position lamp(s) not working both (1.1.A.3b)**Advice** Front Brake lining(s) wearing thin (3.5.1g)**Advice** Rear Brake lining(s) wearing thin (3.5.1g)**Fail** Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Advice** Front Brake lining(s) wearing thin (3.5.1g)**MOT #10** 2016-05-19 10:47**MOT test number** 146127848047**Result** ✓ Passed**MOT #9** 2016-05-19 10:47**MOT test number** 685631208452**Result** ✗ Failed**Pass with rectification** Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2015-06-09 12:22**MOT test number** 655290665147**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2015-06-09 12:22**MOT test number** 165430665196**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-07-08 14:41**MOT test number** 957009484107**Result** ✓ Passed**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #5** 2013-07-09 10:14**MOT test number** 148680693199**Result** ✓ Passed**Notice** Rear most seat belts not fully tested, seats stowed under load liner**MOT #4** 2012-06-22 10:20**MOT test number** 259284672199**Result** ✓ Passed**MOT #3** 2012-06-20 11:58**MOT test number** 209682672158**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Fail** Offside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2011-07-11 15:15
MOT test number	406672591154
Result	✓ Passed

MOT #1	2010-07-10 12:19
MOT test number	894861590143
Result	✓ Passed

- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)
- Notice** REAR SEATS FOLDED AWAY, UNABLE TO FULLY INSPECT R/R SEAT BELT CLIPS
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
2 February 2021

X

MOT

Expired:
8 June 2021

Tax status	Expired at 2 February 2021
Days left	1182 days too late
MOT expiry date	8 June 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN07LDY
Plate since	2019-03-28
Current registration	EN07LDY
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-06-25
Last registration	2020-05-14
Complete history	See info



Registration #1	2007-06-25	27 mi
Registration #2	2010-07-10	21.793 mi
Registration #3	2011-07-11	31.956 mi
Registration #4	2012-06-20	40.193 mi
Registration #5	2012-06-22	40.193 mi
Registration #6	2013-07-09	49.697 mi
Registration #7	2014-07-08	54.172 mi
Registration #8	2015-06-09	57.183 mi
Registration #9	2016-05-19	69.501 mi
Registration #10	2016-05-19	69.501 mi
Registration #11	2016-05-19	69.501 mi
Registration #12	2016-05-19	69.501 mi
Registration #13	2016-05-19	69.501 mi
Registration #14	2016-05-19	69.501 mi
Registration #15	2016-05-19	69.501 mi
Registration #16	2016-05-19	69.501 mi
Registration #17	2016-05-19	69.501 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1725 mm
Length	4650 mm
Wheel base	2700 mm
Kerb weight	1893 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	D4EB7267182