



report date: 2024-03-28

General information

Make	AUDI
Model	A6 TDI S LINE
Colour	Black
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	160 g/km
CO2 label	G





MOT history

MOT expiry date	2024-09-29
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #19	2023-09-30 14:37
MOT test number	378821880298
Result	✓ Passed
Next expiry date	2024-09-29
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2022-08-02 09:41
MOT test number	919429087731
Result	✓ Passed

MOT #17	2022-08-02 09:41
MOT test number	139638944968
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16	2021-07-12 09:20
MOT test number	726255412921
Result	✓ Passed

**MOT #15** 2020-07-20 13:31**MOT test number** 354117016369**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2019-07-29 14:25**MOT test number** 795527994502**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-07-29 11:44**MOT test number** 685423857932**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-07-28 14:31**MOT test number** 470835368068**Result** ✓ Passed**MOT #11** 2017-10-14 09:30**MOT test number** 421866992904**Result** ✓ Passed**MOT #10** 2016-10-29 09:46**MOT test number** 332483369216**Result** ✓ Passed**Advice** Front Inner Tyre worn close to the legal limit both (4.1.E.1)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #9** 2015-10-31 10:33**MOT test number** 101518101161**Result** ✓ Passed**MOT #8** 2014-10-11 10:05**MOT test number** 607944784212**Result** ✓ Passed**Advice** Offside Rear position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**MOT #7** 2013-10-05 12:10**MOT test number** 336018873285**Result** ✓ Passed**MOT #6** 2012-11-01 09:45**MOT test number** 615596402370**Result** ✓ Passed**MOT #5** 2012-07-11 14:19**MOT test number** 246943692441**Result** ✓ Passed**Notice** Fuel tank straps corroded**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Condensation in off side rear lamp cluster**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2012-07-11 09:58**MOT test number** 339153692144**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Notice** Fuel tank straps corroded**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Condensation in off side rear lamp cluster**MOT #3** 2011-07-11 12:21**MOT test number** 675322991176**Result** ✓ Passed**Notice** Fuel tank support straps corroded**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Off side front inner brake disc pitted**Notice** Protective shields fitted under vehicle restricting view**MOT #2** 2010-07-06 14:02**MOT test number** 933687380197**Result** ✓ Passed**MOT #1** 2009-10-12 09:24**MOT test number** 972015189224**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 September 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-30
Last registration	2023-09-30
Complete history	See info



Registration #1	2006-10-30	18 mi
Registration #2	2009-10-12	23.076 mi
Registration #3	2010-07-06	27.533 mi
Registration #4	2011-07-11	39.013 mi
Registration #5	2012-07-11	56.984 mi
Registration #6	2012-07-11	56.984 mi
Registration #7	2012-11-01	61.528 mi
Registration #8	2013-10-05	65.203 mi
Registration #9	2014-10-11	71.018 mi
Registration #10	2015-10-31	76.836 mi
Registration #11	2016-10-31	82.652 mi
Registration #12	2017-10-31	88.468 mi
Registration #13	2018-10-31	94.284 mi
Registration #14	2019-10-31	100.100 mi
Registration #15	2020-10-31	105.916 mi
Registration #16	2021-10-31	111.732 mi
Registration #17	2022-10-31	117.548 mi
Registration #18	2023-09-30	123.364 mi
Registration #19	2023-09-30	123.364 mi
Registration #20	2023-09-30	123.364 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1459 mm
Length	4916 mm
Wheel base	2843 mm
Kerb weight	1540 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	BRE 075302