



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | HYUNDAI |
| Model | I40 CRDI STYLE BLUE DRIVE |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 124 mph |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 134 BHP |
| Max. torque | 325 Nm at 2.500 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | C |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-10-10 |
| Pictures | 26 |
| Listing price | View report |



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-09 |
| Pictures | 2 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-06 |
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 30 |
| Total items failed | 5 |

| | |
|------------------|--|
| MOT #10 | 2023-11-07 16:23 |
| MOT test number | 135882702765 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-06 |
| Advice | Suspension parts getting rusty in places |

| | |
|-----------------|--|
| MOT #9 | 2023-11-03 16:14 |
| MOT test number | 686126038471 |
| Result | ✗ Failed |
| Advice | Suspension parts getting rusty in places |
| Fail | Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges and worn very close to limits (5.2.3 (e)) |
| Fail | Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Worn on edges and worn very close to limits (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #8 | 2022-11-02 15:39 |
| MOT test number | 728997050151 |
| Result | ✓ Passed |
| Advice | Front and rear suspension parts getting very rusty in places |
| Advice | Tyre worn close to legal limit/worn on edge Both rear tyres worn on edges and starting to crack (5.2.3 (e)) |

**MOT #7**

2022-11-02 12:28

MOT test number

887312164365

Result**✗ Failed****Advice**

Front and rear suspension parts getting very rusty in places

Advice

Tyre worn close to legal limit/worn on edge Both rear tyres worn on edges and starting to crack (5.2.3 (e))

Fail

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #6

2021-11-02 15:08

MOT test number

380841971870

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2019-09-23 16:27

MOT test number

398694305119

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

**MOT #4** 2019-09-23 08:49**MOT test number** 926696119605**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))**MOT #3** 2018-09-26 07:40**MOT test number** 820160608344**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2017-10-05 10:16**MOT test number** 653283601532**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit Has inner and outer edge wear. (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre has inner edge wear.**Advice** Offside Front Tyre worn close to the legal limit Has inner and outer edge wear. (4.1.E.1)**Advice** Nearside Rear Tyre perished.



| | |
|-----------------|---|
| MOT #1 | 2016-10-07 10:58 |
| MOT test number | 105501129088 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Rear wiper split |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
6 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 64 |
| MOT expiry date | 6 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-01-01 |
| Current registration | |
| Plate since | 2019-01-01 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2013-08-08 |
| Last registration | 2023-11-07 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2013-08-08 | 11 mi |
| Registration #2 | 2016-10-07 | 80.552 mi |
| Registration #3 | 2017-10-05 | 95.116 mi |
| Registration #4 | 2018-09-26 | 108.576 mi |
| Registration #5 | 2019-09-23 | 117.462 mi |
| Registration #6 | 2019-09-23 | 117.466 mi |
| Registration #7 | 2019-09-23 | 117.466 mi |
| Registration #8 | 2019-09-23 | 117.466 mi |
| Registration #9 | 2019-09-23 | 117.466 mi |
| Registration #10 | 2019-09-23 | 117.466 mi |
| Registration #11 | 2019-09-23 | 117.466 mi |
| Registration #12 | 2019-09-23 | 117.466 mi |
| Registration #13 | 2019-09-23 | 117.466 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 92% |
| Children | 86% |
| Pedestrian | 43% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1815 mm |
| Height | 1470 mm |
| Length | 4770 mm |
| Wheel base | 2770 mm |
| Kerb weight | 1648 kg |
| Max. allowed weight | 2120 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FDCU263340 |