





report date: 2024-03-29

#### General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	Red
Year of manufacture	2016
Top speed	102 mph
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

### Entry 1

Date 2022-04-28

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-06-26
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #6	2023-06-27 15:35	
MOT test number	155822702035	
Result	✓ Passed	
Next expiry date	2024-06-26	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (6	e))	
Minor Nearside Obligatory mirror slightly damaged casing broken (3.3 (b) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))		

MOT #5	2022-05-27 13:32
MOT test number	900984751113
Result	✓ Passed
MOT #4	2022-05-27 13:32
MOT test number	356477490971
Result	<b>X</b> Failed
Pass with rectification (c))	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice
Oil leak, but not excessive (8.4.1 (a) (i))

Advice
Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Minor
Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #2

MOT test number

783157074936

Result

Advice Offside Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))

MOT #1

MOT test number

548554907333

Result

Advice Handbrake lever has very little reserve travel.

Advice Oil leak, but not excessive slight oil leak starting from lower engine at the back. (8.4.1 (a) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



BD16DSZ report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 


CarCheck.co.uk page 9/11



report date: 2024-03-29

### Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-06-23
Last registration	2023-06-27
Complete history	See info



Registration #1	2016-06-23	13 mi
Registration #2	2019-05-17	42.516 mi
Registration #3	2020-04-11	57.665 mi
Registration #4	2021-04-05	72.992 mi
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

### Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1832 mm
Height	1880 mm
Length	4740 mm
Wheel base	2750 mm
Kerb weight	1445 kg
Max. allowed weight	2370 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
Number of axles CarCheck.co.uk	2 page 11/1