





report date: 2022-08-09

General information

Make	MASERATI
Model	COUPE V8 CAMBIO CORSA
Colour	Red
Year of manufacture	2004
Top speed	177 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	385 BHP
Max. torque	451 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.0 mpg
Consumption extra urban	21.7 mpg
Consumption combined	15.2 mpg
CO2 emission	430 g/km
CO2 label	М



CarCheck.co.uk page 1/16



Internet history

_		•		_	-
-	n	т	rv	,	

Elici y I	
Date	2021-10-10
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2024-06-05
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	37
Total items failed	15

MOT #23		2023-06-06 15:56
MOT test	number	607091368121
Result		✓ Passed
Next expi	ry date	2024-06-05
Advice	Offside Front Brake pipe corroded, covered in grease or other material pi	pe to caliper (1.1.11 (c))
Advice (c))	Nearside Front Brake pipe corroded, covered in grease or other material	pipe to caliper (1.1.11
Advice	Power steering component has slight seepage from a component (2.1.5 ((a))

MOT #22	2022-06-17 07:44
MOT test number	214775250795
Result	√ Passed

MOT #21	2021-07-08 09:48
MOT test number	603913578604
Result	✓ Passed
Advice Power steering component has slight seepage from a component (2.1.5 (a))	

Advice Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

CarCheck.co.uk page 3/16



Result

FL54SVY report date: 2022-08-09

Passed

MOT #20 2021-07-08 09:48

MOT test number 440677181873

Result X Failed

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #19 2020-07-11 11:06

MOT test number 423379284033

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Fluid leak, but not excessive Steering rack weeping (8.4.1 (a) (i))

Minor Brake warning device malfunctioning or defective Brake warning lamp is flashing (1.1.4 (a) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/16



MOT #18 2020-07-11 10:35

MOT test number 903966267462

Result × Failed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Minor Brake warning device malfunctioning or defective Brake warning lamp is flashing (1.1.4 (a) (i))

Advice Fluid leak, but not excessive Steering rack weeping (8.4.1 (a) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #17 2019-06-21 16:02

MOT test number 839826760375

Result \rightarrow Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 5/16



MOT #16 2019-05-28 14:14

MOT test number 429631339422

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #15 2018-05-15 10:25

MOT test number 194284605098

Result \(\sqrt{Passed} \)

Advice Both front drop links slightly corroded

Advice Coil spring corroded both front (2.4.C.1b)

MOT #14 2017-04-24 07:50

MOT test number 409094708119

Result
✓ Passed

MOT #13 2017-04-24 07:50

MOT test number 499522675973

Result X Failed

Pass with rectification Parking brake lever has no reserve travel (3.1.6b)

CarCheck.co.uk page 6/16



MOT #12	2016-05-13 15:00
MOT test number	751548208433
Result	✓ Passed
MOT #11	2016-05-13 10:37
MOT test number	235328926293
Result	× Failed
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Fail Nearside Steering rack gaiter split (2.2.D.2d)	

Fail Nearside Steering rack gaiter split (2.2.D.2d)	
MOT #10	2015-04-29 10:09
MOT test number	175029015174
Result	✓ Passed
MOT #9	2013-10-23 10:54
MOT test number	126906693246
Result	✓ Passed
MOT #8	2012-05-14 16:39
MOT test number	239165732138
Result	✓ Passed
MOT #7	2011-09-20 11:16
MOT test number	646713861275
Result	✓ Passed

CarCheck.co.uk page 7/16



MOT test number

Result

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2010-09-14 10:47 **MOT** test number 973197250243 Result ✓ Passed MOT #4 2009-09-16 11:16 **MOT** test number 890019459243 Result ✓ Passed **MOT** #3 2008-10-09 12:46 **MOT test number** 140473588257 ✓ Passed Result **MOT #2 MOT test number**

MOT test number

Result

Fail Offside Rear Lower Tie bar/rod has excessive play in a ball joint (2.4.G.2)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Parking brake lever has no reserve travel (3.1.6b)

CarCheck.co.uk page 8/16



MOT #1 2007-10-25 15:14

MOT test number 140018097224

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 9/16





Tax & MOT check





Tax status	Expired at 6 April 2023
Days left	358 days too late
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16




Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MASERATI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner history

For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Downloshere.	

Plate changes	More info >
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 13/16



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 14/16



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-11-05
Last registration	2023-06-06
Complete history	See info



Registration #1	2004-11-05	15 mi
Registration #2	2007-10-25	18.637 mi
Registration #3	2008-10-06	22.213 mi
Registration #4	2008-10-09	22.215 mi
Registration #5	2009-09-16	24.319 mi
Registration #6	2010-09-14	26.200 mi
Registration #7	2011-09-15	27.808 mi
Registration #8	2011-09-20	27.811 mi
Registration #9	2012-05-14	30.804 mi
Registration #10	2013-10-23	33.223 mi
Registration #11	2015-04-29	35.330 mi
Registration #12	2016-05-13	38.393 mi
Registration #13	2016-05-13	38.393 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 esi
Registration #20		71.777 es
Registration #21		11.777 esi
Registration #22		71.777 es
Registration #23		71,777 esi
Registration #24		71.777 es
Registration #25		11.777 es



Dimensions & weight

Width	1822 mm
Height	1305 mm
Length	4523 mm
Wheel base	2660 mm
Kerb weight	1680 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	88485

CarCheck.co.uk page 16/16