





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO GTI
Colour	White
Year of manufacture	2016
Top speed	147 mph
0 - 100 km/h	6.7 seconds
0 - 60 mph	6.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 kW / 192 HP / 189 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



Internet history


Entry 3

Date 2021-10-13

Pictures 37

Listing price View report










source: cargurus.co.uk

Entry 2

Date	2021-10-12
Pictures	37

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-24
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-25
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #8	2023-10-06 07:50
MOT test number	773163210138
Result	✓ Passed
Next expiry date	2024-10-25
Minor Rear reflector not red in colour both reflectors shaded (4.8.2 (a) (i))	

MOT #7	2023-10-05 09:43
MOT test number	792492461763
Result	× Failed
Minor Rear reflector not red in colour both reflectors shaded (4.8.2 (a) (i))	
Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure bulge in outer sidewall (5.2.3 (d) (ii))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Offside Front Tyre has ply or cords exposed cords exposed on inner edge (5.2.3	(d) (ii))

MOT #6	2022-10-21 08:54
MOT test number	390207810057
Result	✓ Passed
MOT #5	2021-10-26 14:44
MOT test number	517681006947
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4 2021-10-22 14:31

MOT test number 800256573389

Result X Failed

Fail Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #3 2021-01-27 16:13

MOT test number 174755814781

MOT #2 2020-08-24 13:29

MOT test number 591854697309

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-08-20 08:35

MOT test number 322067902508

Result

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

William .	40
Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



owner metery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK ZAS
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-08-27
Last registration	2023-10-06
Complete history	See info



Registration #1	2016-08-27	26 mi
Registration #2	2019-08-20	25.875 mi
Registration #3	2020-08-24	36.353 mi
Registration #4	2021-01-27	40.748 mi
Registration #5		0.074
Registration #6		71,777 66
Registration #7		0.074
Registration #8		71.777 66
Registration #9		11.777 mi
Registration #10		71.777 66
Registration #11		D.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1172 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
CarChack co.uk	pago 11/1

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	DAJA014876