



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 320 CDI EDITION 10
Colour	Blue
Year of manufacture	2008
Top speed	127 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.4 mpg
CO2 emission	254 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-02-02
Pictures	4
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2023-01-03
-----------------	------------

MOT pass rate	69 %
---------------	------

MOT passed	11
------------	----

Failed MOT tests	5
------------------	---

Total advice items	38
--------------------	----

Total items failed	5
--------------------	---

MOT #16	2022-01-04 15:11
---------	------------------

MOT test number	155954940354
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-01-03
------------------	------------

Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
---------------	--

Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
--------------	---

Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
---------------	---

Advice	Nearside rear tyre inner edge heavily worn
---------------	--

Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
--------------	--

Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
---------------	---

Advice	Offside Front Tyre worn close to legal limit/worn on edge and inner edge heavily worn almost through to the ply or cords (5.2.3 (e))
---------------	--

Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
---------------	--

**MOT #15**

2021-12-30 15:36

MOT test number

624985613394

Result**✗ Failed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge and inner edge heavily worn almost through to the ply or cords (5.2.3 (e))
- MAJOR** Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- DANGEROUS** Offside Rear Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))
- Advice** Nearside rear tyre inner edge heavily worn
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #14

2020-10-30 11:57

MOT test number

336010038534

Result**✓ Passed****MOT #13**

2019-12-17 12:42

MOT test number

938716487137

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2019-12-16 12:01

MOT test number

209105142563

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #11

2018-12-12 13:11

MOT test number

375019763773

Result**✓ Passed**

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2018-12-12 13:11

MOT test number

906879796357

Result**✗ Failed**

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2017-11-01 15:54**MOT test number** 900826075250**Result** ✓ Passed**Advice** Under-trays fitted obscuring some underside components**MOT #8** 2016-10-22 11:47**MOT test number** 362404432022**Result** ✓ Passed**MOT #7** 2015-09-25 10:39**MOT test number** 801948530082**Result** ✓ Passed**MOT #6** 2015-09-25 10:39**MOT test number** 339251900174**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2014-09-22 09:00**MOT test number** 976585064268**Result** ✓ Passed**MOT #4** 2013-10-08 09:59**MOT test number** 299331683288**Result** ✓ Passed**MOT #3** 2012-10-04 11:23**MOT test number** 317208372434**Result** ✓ Passed



MOT #2	2011-10-07 15:30
MOT test number	127940381292
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2011-10-07 09:37
MOT test number	755550381212
Result	✗ Failed
Fail	Nearside Stop lamp not working (1.2.1b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
23 May 2022

✕
MOT

Expired:
3 January 2023

Tax status	Expired at 23 May 2022
Days left	707 days too late
MOT expiry date	3 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 KN58CRX
Plate since	2019-06-29
Current registration	 KN58CRX
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-09
Last registration	2022-01-04
Complete history	See info



Registration #1	2008-10-09	16 mi
Registration #2	2011-10-07	38.846 mi
Registration #3	2011-10-07	38.846 mi
Registration #4	2012-10-04	49.317 mi
Registration #5	2013-10-08	58.436 mi
Registration #6	2014-09-22	65.001 mi
Registration #7	2015-09-25	71.858 mi
Registration #8	2015-09-25	71.858 mi
Registration #9	2016-10-22	79.670 mi
Registration #10	2016-10-22	79.670 mi
Registration #11	2016-10-22	79.670 mi
Registration #12	2016-10-22	79.670 mi
Registration #13	2016-10-22	79.670 mi
Registration #14	2016-10-22	79.670 mi
Registration #15	2016-10-22	79.670 mi
Registration #16	2016-10-22	79.670 mi
Registration #17	2016-10-22	79.670 mi
Registration #18	2016-10-22	79.670 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1815 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040672802