



Mercedes-Benz




report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | MERCEDES |
| Model | C C200 K AVANTGARDE SE |
| Colour | Silver |
| Year of manufacture | 2004 |
| Top speed | 144 mph |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 163 BHP |
| Max. torque | 240 Nm at 3.000 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 22.2 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 32.5 mpg |
| CO2 emission | 219 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-23 |
| Pictures | 27 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-31 |
| MOT pass rate | 69 % |
| MOT passed | 18 |
| Failed MOT tests | 8 |
| Total advice items | 41 |
| Total items failed | 8 |

| | |
|------------------|--|
| MOT #26 | 2024-03-04 12:05 |
| MOT test number | 529609288700 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-31 |
| Advice | Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) |
| Advice | Offside Front Wheel bearing has slight play (5.1.3 (a) (i)) |

| | |
|-----------------|---|
| MOT #25 | 2023-03-09 11:44 |
| MOT test number | 387878048496 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

| | |
|-----------------|---|
| MOT #24 | 2023-03-02 11:14 |
| MOT test number | 455191413823 |
| Result | ✗ Failed |
| Advice | Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| MAJOR | Brake pipe excessively corroded both rear (1.1.11 (c)) |
| MAJOR | Suspension arm pin or bush excessively worn both front (5.3.4 (a) (i)) |

**MOT #23** 2022-04-01 10:02**MOT test number** 145072863888**Result** ✓ Passed**Advice** Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #22** 2021-03-04 14:06**MOT test number** 562889944353**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #21** 2021-03-04 11:09**MOT test number** 579939121952**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #20** 2020-03-18 10:31**MOT test number** 338655472348**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2019-03-13 13:29**MOT test number** 844044331951**Result** ✓ Passed

**MOT #18** 2019-03-13 10:53**MOT test number** 330491119481**Result** ✗ Failed

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2018-03-14 10:44**MOT test number** 724339423452**Result** ✓ Passed**MOT #16** 2017-03-20 17:19**MOT test number** 864007835591**Result** ✓ Passed**MOT #15** 2016-03-15 09:24**MOT test number** 144859874024**Result** ✓ Passed**MOT #14** 2015-03-11 09:27**MOT test number** 859590175050**Result** ✓ Passed

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #13 2014-03-21 14:29**MOT test number** 715680484038**Result** ✓ Passed

**MOT #12** 2014-03-15 09:30**MOT test number** 939454774073**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Freeplay in offside front wheel bearing**MOT #11** 2013-03-14 09:35**MOT test number** 875343873024**Result** ✓ Passed**Notice** Nearside front wiper split (not efecting driver's view)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #10** 2012-03-27 08:53**MOT test number** 785407882050**Result** ✓ Passed**Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #9** 2012-03-17 09:35**MOT test number** 558157372030**Result** ✗ Failed**Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Fail** Nearside Front coil spring fractured (2.4.C.1a)

**MOT #8** 2011-03-17 09:54**MOT test number** 639726971077**Result** ✓ Passed**MOT #7** 2010-03-22 12:07**MOT test number** 492741880025**Result** ✓ Passed**MOT #6** 2010-03-18 11:51**MOT test number** 163637070450**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2009-03-19 07:52**MOT test number** 814788479057**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Parking brake noisy on application.**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Offside front tyre tread wearing on edges.



MOT #4 2009-03-17 08:42

MOT test number 941746379020

Result ✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Offside front tyre tread wearing on edges.

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Track rod end ball joint has slight play (2.2.B.1f)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Parking brake noisy on application.

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #3 2008-03-18 16:13

MOT test number 504218978048

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2007-03-14 16:18

MOT test number 374173977082

Result ✓ Passed

Notice Nail in nearside front tyre



| | |
|-------------------------|--------------------------------------|
| MOT #1 | 2007-03-14 16:18 |
| MOT test number | 782233477007 |
| Result | ✗ Failed |
| Pass with rectification | Offside Headlamp aim too high (1.8) |
| Notice | Nail in nearside front tyre |
| Pass with rectification | Nearside Headlamp aim too high (1.8) |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
31 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 31 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  GY04YGN |
| Plate since | 2019-06-29 |
| Current registration |  GY04YGN |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 27 |
| First mileage registration | 2004-03-31 |
| Last registration | 2024-03-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2004-03-31 | 25 mi |
| Registration #2 | 2007-03-14 | 24.655 mi |
| Registration #3 | 2008-03-18 | 31.250 mi |
| Registration #4 | 2009-03-17 | 28.259 mi |
| Registration #5 | 2009-03-19 | 38.248 mi |
| Registration #6 | 2010-03-18 | 44.175 mi |
| Registration #7 | 2010-03-22 | 44.225 mi |
| Registration #8 | 2011-03-17 | 51.941 mi |
| Registration #9 | 2012-03-17 | 62.198 mi |
| Registration #10 | 2012-03-27 | 62.575 mi |
| Registration #11 | 2013-03-14 | 71.032 mi |
| Registration #12 | 2014-03-15 | 76.512 mi |
| Registration #13 | 2014-03-21 | 76.540 mi |
| Registration #14 | 2015-03-11 | 79.286 mi |
| Registration #15 | 2015-03-20 | 80.377 mi |
| Registration #16 | 2015-03-20 | 80.377 mi |
| Registration #17 | 2015-03-20 | 80.377 mi |
| Registration #18 | 2015-03-20 | 80.377 mi |
| Registration #19 | 2015-03-20 | 80.377 mi |
| Registration #20 | 2015-03-20 | 80.377 mi |
| Registration #21 | 2015-03-20 | 80.377 mi |
| Registration #22 | 2015-03-20 | 80.377 mi |
| Registration #23 | 2015-03-20 | 80.377 mi |
| Registration #24 | 2015-03-20 | 80.377 mi |
| Registration #25 | 2015-03-20 | 80.377 mi |
| Registration #26 | 2015-03-20 | 80.377 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1956 mm |
| Height | 1426 mm |
| Length | 4526 mm |
| Wheel base | 2715 mm |
| Kerb weight | 1400 kg |
| Max. allowed weight | 1955 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of axles | 2 |
| Engine number | 27194030243587 |