



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D5 EXECUTIVE
Colour	Blue
Year of manufacture	2011
Top speed	140 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-02
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	18
Total items failed	8

MOT #14	2024-02-14 12:03
MOT test number	552092347694
Result	✓ Passed
Next expiry date	2025-02-20

MOT #13	2023-02-21 08:31
MOT test number	749057663070
Result	✓ Passed
Advice	Direction indicator slightly discoloured both rears (4.4.3 (a))

MOT #12	2022-02-28 18:25
MOT test number	358534401733
Result	✓ Passed

MOT #11	2021-03-24 08:31
MOT test number	752431715429
Result	✓ Passed
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #10** 2021-03-23 09:04**MOT test number** 656713120131**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #9** 2019-12-13 13:53**MOT test number** 747280986731**Result** ✓ Passed**Advice** Offside side repeater deteriorated but light intensity not significantly reduced**MOT #8** 2019-12-05 10:52**MOT test number** 727798308782**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside side repeater deteriorated but light intensity not significantly reduced**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-12-11 12:31**MOT test number** 298784030368**Result** ✓ Passed**Advice** Offside Front tyre worn inner edge**Advice** Nearside Front tyre worn inner edge



MOT #6	2017-11-07 17:08
MOT test number	854587768178
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear registration plate faded but not likely to be misread (6.3.1d)

MOT #5	2017-11-07 13:29
MOT test number	333597865568
Result	✗ Failed
Advice	Rear registration plate faded but not likely to be misread (6.3.1d)
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2016-11-09 11:49
MOT test number	513937921486
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2016-11-08 09:49**MOT test number** 633663012080**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-11-11 12:40**MOT test number** 830101865954**Result** ✓ Passed**MOT #1** 2014-11-03 16:09**MOT test number** 317777204336**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-12-16
Last registration	2024-02-14
Complete history	See info



Registration #1	2011-12-16	26 mi
Registration #2	2014-11-03	37.527 mi
Registration #3	2015-11-11	48.926 mi
Registration #4	2016-11-08	61.025 mi
Registration #5	2016-11-09	61.029 mi
Registration #6	2017-11-07	69.030 mi
Registration #7	2017-11-07	69.035 mi
Registration #8	2018-12-11	75.586 mi
Registration #9	2019-05-29	85.277 mi
Registration #10	2019-05-29	85.277 mi
Registration #11	2019-05-29	85.277 mi
Registration #12	2019-05-29	85.277 mi
Registration #13	2019-05-29	85.277 mi
Registration #14	2019-05-29	85.277 mi
Registration #15	2019-05-29	85.277 mi
Registration #16	2019-05-29	85.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1703 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1032060