



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | MAZDA          |
| Model               | MX-5 I         |
| Colour              | Silver         |
| Year of manufacture | 2007           |
| Top speed           | 130 mph        |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 125 BHP             |
| Max. torque             | 167 Nm at 4.500 rpm |
| Engine capacity         | 1.999 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 26.7 mpg            |
| Consumption extra urban | 47.1 mpg            |
| Consumption combined    | 36.7 mpg            |
| CO2 emission            | 183 g/km            |
| CO2 label               | I                   |





MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-04-23 |
| MOT pass rate      | 78 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 4          |
| Total advice items | 26         |
| Total items failed | 10         |

|                  |                  |
|------------------|------------------|
| MOT #18          | 2023-04-24 11:38 |
| MOT test number  | 766567949674     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-04-23       |

|                 |   |
|-----------------|---|
| MOT #17         | 2022-05-21 15:07  |
| MOT test number | 229867224228  |
| Result          | ✓ Passed  |
| Advice          | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice          | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                   |
| Advice          | Nearside Rear Coil spring corroded (5.3.1 (b) (i))                          |
| Advice          | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |
| Advice          | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                  |
| Advice          | Offside Rear Coil spring corroded (5.3.1 (b) (i))                           |

**MOT #16**

2022-05-12 09:14

**MOT test number**

517841862224

**Result****✗ Failed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2021-06-01 15:02

**MOT test number**

298215709252

**Result****✓ Passed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Brake pipe corroded, covered in grease or other material Grease (1.1.11 (c))
- Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Lower Suspension rod damaged but not seriously weakened bent (5.3.3 (b) (i))

**MOT #14** 2021-06-01 10:26**MOT test number** 999658535926**Result** ✗ Failed**Advice** Brake pipe corroded, covered in grease or other material Grease (1.1.11 (c))**Advice** Offside Rear Lower Suspension rod damaged but not seriously weakened bent (5.3.3 (b) (i))**Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2020-06-03 12:27**MOT test number** 765007418057**Result** ✓ Passed**MOT #12** 2019-05-22 11:33**MOT test number** 937653423356**Result** ✓ Passed**MOT #11** 2018-06-05 11:56**MOT test number** 984579247061**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2018-06-05 11:56**MOT test number** 225878933520**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #9** 2017-05-30 15:35**MOT test number** 868338108423**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened Corroded on inner face (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened Corroded on inner face (3.5.1i)**MOT #8** 2016-06-06 10:54**MOT test number** 790323349866**Result** ✓ Passed**Advice** Rear pads getting low**MOT #7** 2015-06-02 13:14**MOT test number** 399883655125**Result** ✓ Passed**MOT #6** 2014-05-15 16:21**MOT test number** 586015334162**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-05-31 15:36**MOT test number** 289751653455**Result** ✓ Passed**MOT #4** 2012-06-02 12:30**MOT test number** 588104252148**Result** ✓ Passed



|                 |                  |
|-----------------|------------------|
| MOT #3          | 2011-05-19 17:27 |
| MOT test number | 307609831199     |
| Result          | ✓ Passed         |

|                         |   |
|-------------------------|---|
| MOT #2                  | 2011-05-19 17:27  |
| MOT test number         | 465659431173  |
| Result                  | ✗ Failed  |
| Pass with rectification | Offside Headlamp aim too high and too far to the right. (1.8) |
| Pass with rectification | Nearside Headlamp aim too high (1.8)                          |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2010-05-21 12:23 |
| MOT test number | 621881240129     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✗  
**MOT**  
  
Expired:  
23 April 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Valid until 1 June              |
| Days left        | 33                              |
| MOT expiry date  | 23 April 2024                   |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | I          |
| Single payment (12 months)              | £ 320,00,- |
| Single six month payment                | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

|          |  |
|----------|--|
| Damage 1 |  |
| Date     |  |
| Category |  |
| Type     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-09-28 |
| Current registration |            |
| Plate since          | 2019-09-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2007-06-09               |
| Last registration          | 2023-04-24               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2007-06-09 | 21 mi     |
| Registration #2  | 2010-05-21 | 24.634 mi |
| Registration #3  | 2011-05-19 | 32.489 mi |
| Registration #4  | 2012-06-02 | 39.168 mi |
| Registration #5  | 2013-05-31 | 45.964 mi |
| Registration #6  | 2014-05-15 | 52.467 mi |
| Registration #7  | 2015-06-02 | 60.440 mi |
| Registration #8  | 2016-06-06 | 64.998 mi |
| Registration #9  | 2017-05-30 | 71.008 mi |
| Registration #10 | 2018-05-29 | 75.277 mi |
| Registration #11 | 2019-05-29 | 75.277 mi |
| Registration #12 | 2020-05-29 | 75.277 mi |
| Registration #13 | 2021-05-29 | 75.277 mi |
| Registration #14 | 2022-05-29 | 75.277 mi |
| Registration #15 | 2023-05-29 | 75.277 mi |
| Registration #16 | 2024-05-29 | 75.277 mi |
| Registration #17 | 2025-05-29 | 75.277 mi |
| Registration #18 | 2026-05-29 | 75.277 mi |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1720 mm |
| Height              | 1245 mm |
| Length              | 3995 mm |
| Wheel base          | 2330 mm |
| Kerb weight         | 1080 kg |
| Max. allowed weight | 1355 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 2                     |
| Number of seats    | 2                     |
| Number of axles    | 2                     |
| Engine number      | LF 10220147           |