



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Silver
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.997 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-11-08
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-10-12
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-17
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	29
Total items failed	10

MOT #18	2023-11-08 11:49
MOT test number	891856041529
Result	✓ Passed
Next expiry date	2024-11-17
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Undertrays fitted obscuring view
Advice	Underbody and Subframe slightly corroded

MOT #17	2023-11-06 11:28
MOT test number	217606344388
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Front Service brake excessively fluctuating (1.2.1 (e))
Advice	Undertrays fitted obscuring view
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Underbody and Subframe slightly corroded

**MOT #16** 2022-11-18 14:27**MOT test number** 541346378852**Result** ✓ Passed**Advice** Undertrays fitted obscuring view**Advice** Brake pipes greased obscuring view**MOT #15** 2021-11-15 14:39**MOT test number** 653219243863**Result** ✓ Passed**MOT #14** 2021-07-13 16:53**MOT test number** 115241952637**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2020-11-30 16:43**MOT test number** 817414870374**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust middle hanger detached

**MOT #12** 2020-11-30 12:23**MOT test number** 921866941880**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust middle hanger detached**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Horn not working (7.7 (a) (ii))**MOT #11** 2019-04-25 15:40**MOT test number** 539284073171**Result** ✓ Passed**MOT #10** 2018-05-04 15:03**MOT test number** 635609533419**Result** ✓ Passed**MOT #9** 2018-04-30 13:26**MOT test number** 400698093177**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Inner Road wheel cracked edge at bead lip (4.2.A.1a)**MOT #8** 2017-04-20 14:49**MOT test number** 806021602418**Result** ✓ Passed

**MOT #7** 2016-04-28 10:40**MOT test number** 488325639213**Result** ✓ Passed**MOT #6** 2015-05-05 12:27**MOT test number** 218375925459**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-07-12 15:24**MOT test number** 506323494152**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2013-07-25 13:59**MOT test number** 539706203212**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-07-27 16:05**MOT test number** 188119802200**Result** ✓ Passed**Notice** Both rear tyres very close to the legal 1.6 mm limit



MOT #2	2011-07-27 15:07
MOT test number	238128001210
Result	✓ Passed
Advice	Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
Notice	Parking brake imbalance
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1	2010-08-05 10:28
MOT test number	662847110272
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
17 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	17 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-03
Last registration	2023-11-08
Complete history	<a href="#">See info</a>



Registration #1	2007-09-03	6 mi
Registration #2	2010-08-05	25.901 mi
Registration #3	2011-07-27	35.209 mi
Registration #4	2012-07-27	44.796 mi
Registration #5	2013-07-25	45.354 mi
Registration #6	2014-07-12	47.910 mi
Registration #7	2015-05-05	49.707 mi
Registration #8	2016-04-28	55.439 mi
Registration #9	2017-04-20	58.906 mi
Registration #10	2018-04-30	64.105 mi
Registration #11	2018-05-04	64.107 mi
Registration #12	2019-05-20	70.277 mi
Registration #13	2019-05-20	70.277 mi
Registration #14	2019-05-20	70.277 mi
Registration #15	2019-05-20	70.277 mi
Registration #16	2019-05-20	70.277 mi
Registration #17	2019-05-20	70.277 mi
Registration #18	2019-05-20	70.277 mi
Registration #19	2019-05-20	70.277 mi
Registration #20	2019-05-20	70.277 mi
Registration #21	2019-05-20	70.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030589725