



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-22
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-22
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	19
Total items failed	15

MOT #16	2023-08-16 13:00
MOT test number	629577206114
Result	✓ Passed
Next expiry date	2024-08-22

MOT #15	2022-08-17 14:48
MOT test number	218982641139
Result	✓ Passed

MOT #14	2022-08-17 14:48
MOT test number	579914315082
Result	✗ Failed

- Pass with rectification Central Exhaust system insecure (6.1.2 (a))
- Pass with rectification Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))
- Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #13	2021-08-23 15:38
MOT test number	108693851537
Result	✓ Passed

**MOT #12** 2020-12-04 11:21**MOT test number** 865437256109**Result** ✓ Passed**Minor** Nearside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Offside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2019-12-02 15:34**MOT test number** 268028782168**Result** ✓ Passed**MOT #10** 2019-12-02 10:39**MOT test number** 838638759685**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2018-12-07 11:06**MOT test number** 811366703988**Result** ✓ Passed**MOT #8** 2018-12-07 11:06**MOT test number** 843303946466**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #7** 2017-12-02 11:13**MOT test number** 283851993725**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-12-16 15:39**MOT test number** 235684608976**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-12-07 16:46**MOT test number** 384628672994**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Side repeater not working (1.4.A.2c)**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Power steering fluid level below minimum (2.3.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #4** 2015-11-25 11:23**MOT test number** 419595676068**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Undertrays fitted

**MOT #3** 2014-11-22 10:07**MOT test number** 248606124342**Result** ✓ Passed**MOT #2** 2013-11-25 14:17**MOT test number** 186529423334**Result** ✓ Passed**MOT #1** 2013-02-18 15:55**MOT test number** 259309143097**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
22 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	22 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-02-15
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2010-02-15	7 mi
Registration #2	2013-02-18	44.358 mi
Registration #3	2013-11-25	54.092 mi
Registration #4	2014-11-22	59.950 mi
Registration #5	2015-11-25	67.210 mi
Registration #6	2016-12-07	70.234 mi
Registration #7	2016-12-16	70.241 mi
Registration #8	2017-12-02	79.609 mi
Registration #9	2018-12-07	93.268 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AS14346