





General information

Make	VAUXHALL
Model	MOKKA DESIGN NAV ECOTEC S/S
Colour	White
Year of manufacture	2018
Top speed	122 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.900 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	150 g/km
CO2 label	F





AY68YXC report date: 2024-03-28

Entry 1	2021-05-28		
Date	10		
Listing price	View report		
Since 1990 by the second secon	Approved Finance Parter EVOLUTION FUNDING	<image/> <image/> <image/> <image/> <section-header><section-header><image/><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header>	<image/> <image/> <image/> <image/> <text><text></text></text>



MOT history

MOT expiry date	2024-05-31
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	7
Total items failed	1

МОТ #4	2023-05-23 11:57
MOT test number	295065938485
Result	✓ Passed
Next expiry date	2024-05-31
AdviceNearside Front Tyre slightly damaged/cracking or perishing cracking on or wearing slightly on edges. (5.2.3 (d) (ii))AdviceOffside Rear Tyre slightly damaged/cracking or perishing cracking on out	
Advice Offside Front Tyre slightly damaged/cracking or perishing cracking on our slightly on edges. (5.2.3 (d) (ii))	

MOT #3	2023-05-23 11:57
MOT test number	313918257881
Result	🗙 Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing cracking o wearing slightly on edges. (5.2.3 (d) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking on o	outer sidewall. (5.2.3 (d) (ii))
Pass with rectification Windscreen washer provides insufficient washer liqu	id (3.5 (a))
Advice Offside Front Tyre slightly damaged/cracking or perishing cracking on outer sidewall and wearing slightly on edges. (5.2.3 (d) (ii))	

MOT #2	2022-05-20 12:34
MOT test number	839213992356
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #1	2021-06-01 15:34
MOT test number	489233069202
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	MOT Expires: 31 May 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET O
Category	LAMP
Туре	
Damage 2	VAMPLE
Date	
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	₩ UK
Ender class	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-09-14
Last registration	2023-05-23
Complete history	See info



Registration #1	2018-09-14	15 mi
Registration #2		11.117 est
Registration #3	2021-06-01	21.249 mi
Registration #4		11.777 esi
Registration #5		11.777 esi
Registration #6		11.277 esi





Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	2038 mm
Height	1658 mm
Length	4275 mm
Wheel base	2555 mm
Kerb weight	1319 kg
Max. allowed weight	1828 kg
Additional information	
Additional information Fuel tank capacity	53
	53 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5