





report date: 2024-03-29

#### General information

Make	RENAULT
Model	CAPTUR DYNAMIQUE NAV DCI
Colour	Orange
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/11



### Internet history

#### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2025-04-05
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #7	2024-03-26 17:03
MOT test number	488933390298
Result	✓ Passed
Next expiry date	2025-04-05
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #6		2024-03-26 14:19
MOT test	number	440124547238
Result		<b>X</b> Failed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge on 3mm 205/55/17 (5.2.3 (e))		
<b>Fail</b> Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut inner edge 205/55/17 (5.2.3 (d) (i))		

MOT "		2022 02 20 12 22
MOT #5		2023-03-28 13:22
MOT test	number	671781437938
Result		✓ Passed
Advice	Offside Front tyre sidewall scrubed	
Advice	Nearside Rear Road wheel slightly distorted buckled and bead rim slightly d	idstorted (5.2.2 (c) (i))

CarCheck.co.uk page 3/11



**MOT #4** 2022-04-04 15:05

**MOT test number** 528987936209

MOT #3 2021-04-06 12:28

**MOT test number** 957617751255

**Result** ✓ Passed

MOT #2 2020-05-20 11:50

MOT test number 178260729938

Result \( \sqrt{Passed} \)

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2020-05-20 09:00

**MOT test number** 288178131362

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	5 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
*************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	OK SIE
Plate since	
	Moro info

CarCheck.co.uk page 8/11



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-04-27
Last registration	2024-03-26
Complete history	See info



Registration #1	2016-04-27	10 mi
Registration #2	2020-05-20	42.838 mi
Registration #3	2020-05-20	42.838 mi
Registration #4		11.777 es
Registration #5	2021-04-06	47.096 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		0.074
Registration #9		11.777 au

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1178 kg
Max. allowed weight	1727 kg

# Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles 2

Engine number D109887