



Mercedes-Benz

GKIOVST


report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 109 CDI EXTRA LONG TRAVELINER
Colour	Red
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	237 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-17
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-06
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	43
Total items failed	25

MOT #20	2023-08-07 13:39
MOT test number	870978031029
Result	✓ Passed
Next expiry date	2024-08-06
Advice	Offside Front Seat belt slightly damaged Drivers seat belt (7.1.2 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #19	2023-08-07 11:19
MOT test number	544886476967
Result	✗ Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Rear Seat belt buckle missing rear facing seat passengers side rear (7.1.2 (d))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Seat belt slightly damaged Drivers seat belt (7.1.2 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #18	2022-08-05 14:54
MOT test number	519067192617
Result	✓ Passed

**MOT #17**

2022-08-02 13:23

MOT test number

709480441403

Result

✗ Failed

- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Fail** Front Fluid leak harmful to the environment or a risk to other road users diesel (8.4.1 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail** Rear Oil leaking excessively from transmission diff (8.4.1 (a) (i))
- Fail** Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #16

2021-08-07 08:55

MOT test number

368753283300

Result

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2021-08-07 08:55

MOT test number

357772457753

Result**✗ Failed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14

2020-07-06 11:11

MOT test number

456924680811

Result**✓ Passed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Suspension component pin or bush slightly worn rear differential (5.3.4 (a) (i))
- Advice** Seat belt webbing slightly damaged or frayed drivers (7.1.2 (b) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Suspension component pin or bush slightly worn rear differential (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive rear differential (8.4.1 (a) (i))

**MOT #13**

2020-06-24 10:24

MOT test number

745767698166

Result**✗ Failed**

- Advice** Offside Suspension component pin or bush slightly worn rear differential (5.3.4 (a) (i))
- Advice** Seat belt webbing slightly damaged or frayed drivers (7.1.2 (b) (ii))
- Advice** Oil leak, but not excessive rear differential (8.4.1 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Suspension component pin or bush slightly worn rear differential (5.3.4 (a) (i))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #12

2019-05-02 10:38

MOT test number

710370097125

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11**

2019-04-29 14:21

MOT test number

504939144023

Result**✗ Failed**

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

MOT #10

2018-04-12 17:10

MOT test number

637723062631

Result**✓ Passed****MOT #9**

2017-04-11 10:07

MOT test number

673509502124

Result**✓ Passed****MOT #8**

2017-04-11 10:07

MOT test number

378009769070

Result**✗ Failed**

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Front Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

**MOT #7** 2016-04-06 15:55**MOT test number** 450224531598**Result** ✓ Passed**MOT #6** 2016-04-06 14:26**MOT test number** 900123817782**Result** ✗ Failed**Fail** Nearside Front front brake binding (3.7.B.1)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #5** 2015-02-11 10:53**MOT test number** 547222745086**Result** ✓ Passed**MOT #4** 2014-02-07 11:31**MOT test number** 987478834097**Result** ✓ Passed**MOT #3** 2013-02-14 10:48**MOT test number** 437565643025**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-02-22 12:00**MOT test number** 145263752458**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2011-02-28 14:13
MOT test number	145199651089
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2024

✓

MOT

Expires:
6 August 2024

Tax status	Expired at 1 January 2024
Days left	119 days too late
MOT expiry date	6 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2024-03-28
Current registration	 XXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-03-01
Last registration	2023-08-07
Complete history	See info



Registration #1	2010-03-01	11 mi
Registration #2	2011-02-28	32.632 mi
Registration #3	2012-02-22	64.136 mi
Registration #4	2013-02-14	102.526 mi
Registration #5	2014-02-07	156.353 mi
Registration #6	2015-02-11	216.139 mi
Registration #7	2016-04-06	253.524 mi
Registration #8	2016-04-06	253.524 mi
Registration #9	2017-04-11	281.491 mi
Registration #10	2017-04-11	281.491 mi
Registration #11	2018-04-12	285.765 mi
Registration #12	2019-05-29	29.277 mi
Registration #13	2019-05-29	29.277 mi
Registration #14	2019-05-29	29.277 mi
Registration #15	2019-05-29	29.277 mi
Registration #16	2019-05-29	29.277 mi
Registration #17	2019-05-29	29.277 mi
Registration #18	2019-05-29	29.277 mi
Registration #19	2019-05-29	29.277 mi
Registration #20	2019-05-29	29.277 mi
Registration #21	2019-05-29	29.277 mi
Registration #22	2019-05-29	29.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1906 mm
Height	1872 mm
Length	5223 mm
Kerb weight	1965 kg
Max. allowed weight	2940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2
Engine number	64698051824950