



report date: 2024-03-28

General information

Make	MINI
Model	COOPER D
Colour	Green
Year of manufacture	2013
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-07-23
Pictures	35
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2024-08-16
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	14
Total items failed	7

MOT #13	2023-07-29 11:47
MOT test number	449221946513
Result	✓ Passed
Next expiry date	2024-08-16
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12	2023-07-28 15:05
MOT test number	686133621169
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #11	2022-08-17 08:56
MOT test number	832048768048
Result	✓ Passed

**MOT #10** 2022-08-14 14:13**MOT test number** 874379575955**Result** ✗ Failed**Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres 175/65/15 cracking or perishing (5.2.3 (d) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened inner face pitted and scored (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2021-12-23 11:43**MOT test number** 573516033737**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Upper Stop light not working**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2020-11-20 15:24**MOT test number** 868994756893**Result** ✓ Passed**MOT #7** 2020-11-20 15:24**MOT test number** 668426400916**Result** ✗ Failed**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #6** 2019-10-11 10:02**MOT test number** 625443442727**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2018-10-03 09:25**MOT test number** 769369135148**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #4** 2018-10-03 09:24**MOT test number** 228209275160**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) all not working (4.3.1 (a) (iii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #3** 2017-04-06 16:40**MOT test number** 483709682254**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2017-04-06 16:40**MOT test number** 579392240225**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #1	2016-03-09 10:23
MOT test number	930108210833
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
16 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	16 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>VO13DYG</b>
Plate since	2019-09-29
Current registration	<b>VO13DYG</b>
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-26
Last registration	2023-07-29
Complete history	<a href="#">See info</a>



Registration #1	2013-03-26	20 mi
Registration #2	2016-03-09	24.928 mi
Registration #3	2017-04-06	33.738 mi
Registration #4	2017-04-06	33.738 mi
Registration #5	2018-10-03	42.224 mi
Registration #6	2018-10-03	42.224 mi
Registration #7	2019-10-11	53.221 mi
Registration #8	2020-11-20	63.076 mi
Registration #9	2020-11-20	63.076 mi
Registration #10	2020-11-20	63.076 mi
Registration #11	2020-11-20	63.076 mi
Registration #12	2020-11-20	63.076 mi
Registration #13	2020-11-20	63.076 mi
Registration #14	2020-11-20	63.076 mi
Registration #15	2020-11-20	63.076 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	70428440