





report date: 2024-03-28

### General information

Make	MINI
Model	MINI (R59) ONE
Colour	Grey
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



# Internet history

### Entry 4

Date 2023-12-30

Pictures 1

Listing price <u>View report</u>



### source: cargurus.co.uk

### Entry 3

Date	2022-11-14
Pictures	0

Listing price <u>View report</u>

### source: carcraft.co.uk

### Entry 2

Date 2022-08-11

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk


### Entry 1

Date	2021-09-08
Pictures	33
Listing price	View report

CarCheck.co.uk page 2/12









source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #12		2023-10-05 15:23
MOT test	number	844105656302
Result		✓ Passed
Next expi	ry date	2024-10-04
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2023-10-04 12:02	
MOT test number	108279400409	
Result	<b>X</b> Failed	
Advice Oil leak, but not excessive (8.	4.1 (a) (i))	
Advice Nearside Rear Tyre slightly da	maged/cracking or perishing (5.2.3 (d) (ii))	
Fail Central Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))		
Advice Front Registration plate deter	iorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/12



MOT #10 2022-10-04 14:25

**MOT test number** 919351471679

Result \rightarrow Passed

**Advice** Rear Tailgate struts are weak

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #9 2022-10-04 08:12

MOT test number 556314746526

Result X Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**Advice** Rear Tailgate struts are weak

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #8 2021-08-04 15:12

MOT test number 171926588623

Result 

Passed

MOT #7 2020-12-11 14:23

MOT test number 351501279593

Result 

Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2018-12-17 13:26

**MOT test number** 216847889506

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



RF12FZC

report date: 2024-03-28

MOT #5 2017-12-19 14:45

**MOT test number** 261830963860

**MOT #4** 2017-08-17 10:56

**MOT test number** 707753268955

Result 

Passed

**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Outer Road tyre side wall damaged.

**Advice** Items removed from driver's view prior to test

MOT #3 2016-08-15 14:47

**MOT test number** 117938006188

**Result** ✓ Passed

**Advice** Front Brake pads worn low

MOT #2 2016-08-15 13:52

**MOT test number** 177525884999

Result X Failed

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Front Brake pads worn low

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #1** 2015-08-07 09:36

**MOT test number** 376079315285

**Result** ✓ Passed

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	4 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



### Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



RF12FZC

report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

RF12FZC

report date: 2024-03-28

# For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>. More info > Plate changes See in this check if this MINI had different number plates.

More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-07-30
Last registration	2023-10-05
Complete history	See info



Registration #1	2012-07-30	13 mi
Registration #2	2015-08-07	31.641 mi
Registration #3	2016-08-15	50.153 mi
Registration #4	2016-08-15	50.153 mi
Registration #5	2017-08-17	70.998 mi
Registration #6	2017-12-19	75.148 mi
Registration #7	2018-12-17	77.521 mi
Registration #8	2020-12-11	101.097 mi
Registration #9	2021-08-04	107.487 mi
Registration #10		11.777 es
Registration #10 Registration #11		11.777 ea 11.777 ea
-		11.77 m
Registration #11		11.77 es 11.77 es 11.77 es
Registration #11 Registration #12		11.77 es 11.77 es 11.77 es 11.77 es
Registration #11 Registration #12 Registration #13		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #11 Registration #12 Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA024J283