



report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 3 SW
Colour	Red
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	255 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-15
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-09
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	44
Total items failed	12

MOT #172023-06-02 16:32

MOT test number626583815509

Result✓ Passed

Next expiry date2024-06-09

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm front bush deteriorated (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** O/S/F wheel arch liner damaged but not about to fall off
- Advice** Nearside Front Road wheel slightly distorted Inner bead lip damaged (5.2.2 (c) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases Front section joint blowing/bolt snapped (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm front bush deteriorated (5.3.4 (a) (i))

**MOT #16**

2023-06-01 08:41

MOT test number

802379772856

Result

✗ Failed

- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases Front section joint blowing/bolt snapped (6.1.2 (a))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm front bush deteriorated (5.3.4 (a) (i))
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall split badly and pressure low (5.2.3 (d) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm front bush deteriorated (5.3.4 (a) (i))
- Advice** O/S/F wheel arch liner damaged but not about to fall off
- Advice** Nearside Front Road wheel slightly distorted Inner bead lip damaged (5.2.2 (c) (i))

MOT #15

2022-06-01 09:20

MOT test number

519563033575

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases downpipe broken stud (6.1.2 (a))



MOT #14	2021-06-10 14:43
MOT test number	274848393000
Result	✓ Passed
Advice	Both rear lower radius arm front bushes beginning to wear and split

MOT #13	2020-01-28 10:35
MOT test number	713953985866
Result	✓ Passed
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bushes (5.3.4 (a) (i))

MOT #12	2020-01-28 09:23
MOT test number	701142180501
Result	✗ Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bushes (5.3.4 (a) (i))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #11**

2019-01-25 16:04

MOT test number

550262447908

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush worn (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush worn (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush worn (5.3.4 (a) (i))

MOT #10

2019-01-25 13:07

MOT test number

564531485799

Result

✗ Failed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush worn (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush worn (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush worn (5.3.4 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #9** 2018-01-30 16:30**MOT test number** 528371106889**Result** ✓ Passed**MOT #8** 2017-01-20 15:16**MOT test number** 436991432997**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both on inner edges (4.1.E.1)**MOT #7** 2016-01-19 15:48**MOT test number** 389888172093**Result** ✓ Passed**Advice** Nearside front tyre worn on edge**MOT #6** 2016-01-19 11:30**MOT test number** 232942948384**Result** ✗ Failed**Advice** Nearside front tyre worn on edge**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #5** 2015-01-13 15:33**MOT test number** 779373615004**Result** ✓ Passed**MOT #4** 2015-01-13 12:55**MOT test number** 379753815086**Result** ✗ Failed**Fail** Front registration plate deteriorated (6.3.1d)



MOT #3	2014-02-06 08:04
MOT test number	317257934074
Result	✓ Passed

MOT #2	2014-02-05 08:27
MOT test number	106596834097
Result	✗ Failed
<div><div>Fail</div> Rear registration plate deteriorated (6.3.1d)</div> <div><div>Advice</div> Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div>	

MOT #1	2013-08-02 09:38
MOT test number	687194213250
Result	✓ Passed
<div><div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-28
Current registration	XXXX XX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-21
Last registration	2023-06-02
Complete history	See info



Registration #1	2010-09-21	19 mi
Registration #2	2013-08-02	16.500 mi
Registration #3	2014-02-05	17.616 mi
Registration #4	2014-02-06	17.616 mi
Registration #5	2015-01-13	33.949 mi
Registration #6	2015-01-13	33.949 mi
Registration #7	2016-01-19	52.477 mi
Registration #8	2016-01-19	52.447 mi
Registration #9	2017-01-20	67.628 mi
Registration #10	2018-01-30	84.515 mi
Registration #11	2019-01-20	95.377 mi
Registration #12	2019-01-20	95.377 mi
Registration #13	2019-01-20	95.377 mi
Registration #14	2019-01-20	95.377 mi
Registration #15	2019-01-20	95.377 mi
Registration #16	2019-01-20	95.377 mi
Registration #17	2019-01-20	95.377 mi
Registration #18	2019-01-20	95.377 mi
Registration #19	2019-01-20	95.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1525 mm
Length	4490 mm
Wheel base	2650 mm
Kerb weight	1509 kg
Max. allowed weight	1940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4FBAZ246525