





report date: 2024-03-29

## General information

| Make                | FORD            |
|---------------------|-----------------|
| Model               | FUSION FUSION + |
| Colour              | Blue            |
| Year of manufacture | 2009            |
| Top speed           | 103 mph         |
| 0 - 60 mph          | 14.7 seconds    |
| Gearbox             | 5 speed Manual  |

## Engine & fuel consumption

| Power                   | 79 BHP              |
|-------------------------|---------------------|
| Max. torque             | 124 Nm at 3.500 rpm |
| Engine capacity         | 1.388 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 32.8 mpg            |
| Consumption extra urban | 49.6 mpg            |
| Consumption combined    | 41.5 mpg            |
| CO2 emission            | 149 g/km            |
| CO2 label               | F                   |



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

#### Entry 1

| Date          | 2021-06-23  |
|---------------|-------------|
| Pictures      | 1           |
| Listing price | View report |



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

|    | _ |     |    |     |
|----|---|-----|----|-----|
| MO | 1 | hic | to | r\/ |
|    |   |     |    | ıv. |
|    |   |     |    | . , |

| MOT expiry date    | 2024-10-03 |
|--------------------|------------|
| MOT pass rate      | 81 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 3          |
| Total advice items | 15         |
| Total items failed | 5          |

| MOT #16          | 2023-09-25 09:45 |
|------------------|------------------|
| MOT test number  | 486307157708     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-10-03       |

| MOT #15  | 2022-09-30 09:24 |
|--|------------------|
| MOT test number  | 933248975879     |
| Result   | ✓ Passed         |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #14  |  | 2021-10-04 12:40 |
|----------|--|------------------|
| MOT test | number   | 482913195556     |
| Result   |  | ✓ Passed         |
|          |  |                  |
| MOT #13  |  | 2021-02-10 12:22 |
| MOT test | number   | 580974147476     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-29

 MOT #12
 2020-02-12 09:12

 MOT test number
 970195638433

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

 MOT #10
 2019-02-11 12:10

 MOT test number
 438355374970

 Result
 ✓ Passed

MOT #9 2018-02-12 09:00

MOT test number 505809657922

MOT #8 2017-02-14 14:03

**MOT test number** 274082075830

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Fail Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

631921104285

Result

Advice Internal headlight switch altered for mot test

Advice Nearside Rear child seat fitted

MOT #5

MOT test number

445183535066

Result

Notice O/s front wheel rim damaged

Notice Rear tyres cracking slightly

MOT test number 676263735081

Result X Failed

Notice O/s front wheel rim damaged

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Rear tyres cracking slightly

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/13



report date: 2024-03-29

| MOT #3          | 2014-02-05 14:39 |
|-----------------|------------------|
| MOT test number | 855056034071     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2013-02-14 15:48 |
| MOT test number | 399095643077     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2012-11-12 12:46 |
| MOT test number | 657487212329     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 6/13



report date: 2024-03-29

## Tax & MOT check



| Tax status       | Valid until 1 April |
|------------------|---------------------|
| Days left        | 336                 |
| MOT expiry date  | 3 October 2024      |
| Full MOT history | See MOT history     |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



EA59FYM report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report |           | ave? |
|---|-----------|------|
|   |           |      |
| manus .   |           |      |
|   |           |      |
|   |           |      |
| ********  |           |      |
|   |           |      |
| ***************************************   |           |      |
|   | More info | >    |
| Plate changes   |           |      |
| See in this check if this FORD had different number plates.   |           |      |
| Number of plates  |           |      |
| Current registration  | UK UK     |      |
| Plate since   |           |      |
| Current registration  | UK UK     |      |
| Plate since   |           |      |
|   | More info | >    |

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 17         |
| First mileage registration | 2009-12-14 |
| Last registration          | 2023-09-25 |
| Complete history           | See info   |



| Registration #1  | 2009-12-14 | 7 mi      |
|------------------|------------|-----------|
| Registration #2  | 2012-11-12 | 7.725 mi  |
| Registration #3  | 2013-02-14 | 8.176 mi  |
| Registration #4  | 2014-02-05 | 10.535 mi |
| Registration #5  | 2015-02-02 | 12.230 mi |
| Registration #6  | 2016-01-29 | 15.875 mi |
| Registration #7  | 2017-02-14 | 27.721 mi |
| Registration #8  | 2017-02-14 | 27.721 mi |
| Registration #9  | 2018-02-12 | 37.566 mi |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
| Registration #16 |            | D.777 es  |
| Registration #17 |            | 91.777 es |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1952 mm |
|---------------------|---------|
| Height              | 1534 mm |
| Length              | 4020 mm |
| Wheel base          | 2485 mm |
| Kerb weight         | 1200 kg |
| Max. allowed weight | 1605 kg |

# Additional information

| Fuel tank capacity                | 45 l                  |           |
|-----------------------------------|-----------------------|-----------|
| Fuel delivery                     | Multi-Point Injection |           |
| Number of doors                   | 5                     |           |
| Number of seats<br>CarCheck.co.uk | 5 pa                  | age 13/13 |