



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 SE
Colour	Blue
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F





MOT history

MOT expiry date	2021-11-04
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	39
Total items failed	34

MOT #22	2020-11-02 12:29
MOT test number	471452158821
Result	✓ Passed
Next expiry date	2021-11-04

MOT #21	2019-10-29 16:30
MOT test number	884162481286
Result	✓ Passed

MOT #20	2019-10-28 12:36
MOT test number	866638165113
Result	✗ Failed

- Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #19** 2018-11-05 14:03**MOT test number** 616407759304**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #18** 2018-11-05 09:30**MOT test number** 462042728041**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #17** 2017-12-11 16:16**MOT test number** 931360194428**Result** ✓ Passed

**MOT #16**

2017-11-30 11:16

MOT test number

256318957446

Result

✗ Failed

- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside front brake excessively fluctuating (3.7.B.3)
- Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside front brake excessively fluctuating (3.7.B.3)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Steering rack insecure (2.2.B.1a)

MOT #15

2016-12-23 10:57

MOT test number

263782976198

Result

✓ Passed

- Advice** Oil leak
- Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake is pulling
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #14 2016-12-16 16:12

MOT test number 253319138980

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside Front brake is pulling
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Steering rack gaiter split (2.2.D.2d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Steering rack gaiter split (2.2.D.2d)
- Advice** Oil leak

MOT #13 2015-12-22 19:19

MOT test number 204563392202

Result ✓ Passed

**MOT #12**

2015-11-19 11:17

MOT test number

847713053196

Result**✗ Failed**

- Fail** Nearside Front Headlamp aim too high (1.8)
- Fail** Offside Rear Shock absorber casing corroded externally so the unit does not function (2.7.2a)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Front Power steering pump drive system defective (2.3.6)
- Fail** Front Power steering pump leaking from a failed joint (2.3.3b)

MOT #11

2014-10-01 09:47

MOT test number

986294374295

Result**✓ Passed**

- Notice** Engine oil leak
- Advice** Steering pivot point has slight play (2.2.B.1g)

MOT #10

2014-09-30 09:28

MOT test number

485063974255

Result**✗ Failed**

- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Headlamp insecure (1.7.3)
- Fail** Rear brake binding (3.7.B.1)
- Notice** Engine oil leak
- Advice** Steering pivot point has slight play (2.2.B.1g)
- Fail** Nearside Steering pivot point has excessive play (2.2.B.1g)

**MOT #9** 2013-10-07 15:10**MOT test number** 439370283274**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2012-10-19 11:08**MOT test number** 129743092254**Result** ✓ Passed**MOT #7** 2012-10-19 11:08**MOT test number** 728933292276**Result** ✗ Failed**Pass with rectification** Nearside Rear Headlamp aim too high (1.8)**MOT #6** 2011-10-19 16:31**MOT test number** 965982991297**Result** ✓ Passed**Advice** Offside Front Steering pivot point has slight play (2.2.B.1g)**Advice** Nearside Front Steering pivot point has slight play (2.2.B.1g)**MOT #5** 2011-10-19 08:22**MOT test number** 256962991274**Result** ✗ Failed**Fail** Offside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Nearside Front Steering pivot point has slight play (2.2.B.1g)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Steering pivot point has slight play (2.2.B.1g)

**MOT #4** 2010-10-22 10:09**MOT test number** 264975990212**Result** ✓ Passed**Notice** Slight play in nsf tie rod**Notice** Front exhaust flexi pipe starting to split**MOT #3** 2009-10-14 11:50**MOT test number** 734167889223**Result** ✓ Passed**MOT #2** 2008-10-17 10:18**MOT test number** 344751398451**Result** ✓ Passed**MOT #1** 2008-10-06 13:15**MOT test number** 890250888288**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Coolant leak**Fail** Nearside Headlamp not in good working order adversely affecting beam image (1.2.4a)**Fail** Nearside Headlamp aim not tested (1.8.A.1c)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Nearside Headlamp insecure (1.7.3)



Tax & MOT check

X

Untaxed

Tax expired:
25 February 2021

X

MOT

Expired:
4 November 2021

Tax status	Expired at 25 February 2021
Days left	1160 days too late
MOT expiry date	4 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KV55RBF
Plate since	2024-03-29
Current registration	KV55RBF
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-10-18
Last registration	2020-11-02
Complete history	See info



Registration #1	2005-10-18	11 mi
Registration #2	2008-10-06	25.566 mi
Registration #3	2008-10-17	25.848 mi
Registration #4	2009-10-14	32.003 mi
Registration #5	2010-10-22	38.394 mi
Registration #6	2011-10-19	45.135 mi
Registration #7	2011-10-19	45.136 mi
Registration #8	2012-10-19	50.279 mi
Registration #9	2013-10-07	56.149 mi
Registration #10	2014-09-30	62.990 mi
Registration #11	2014-10-01	62.992 mi
Registration #12	2015-10-01	62.992 mi
Registration #13	2016-10-01	62.992 mi
Registration #14	2017-10-01	62.992 mi
Registration #15	2018-10-01	62.992 mi
Registration #16	2019-10-01	62.992 mi
Registration #17	2020-10-01	62.992 mi
Registration #18	2021-10-01	62.992 mi
Registration #19	2022-10-01	62.992 mi
Registration #20	2023-10-01	62.992 mi
Registration #21	2024-10-01	62.992 mi
Registration #22	2025-10-01	62.992 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1049 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	FE010119262
---------------	-------------