



General information

|                     |                |
|---------------------|----------------|
| Make                | FIAT           |
| Model               | PUNTO ACTIVE   |
| Colour              | Grey           |
| Year of manufacture | 2010           |
| Top speed           | 103 mph        |
| 0 - 60 mph          | 13.2 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 77 BHP              |
| Max. torque             | 115 Nm at 3.250 rpm |
| Engine capacity         | 1.368 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 38.2 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 49.6 mpg            |
| CO2 emission            | 132 g/km            |
| CO2 label               | E                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-30                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |

**AA**

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: cargurus.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-08-08 |
| MOT pass rate      | 69 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 5          |
| Total advice items | 43         |
| Total items failed | 3          |

|                  |  |
|------------------|--|
| MOT #16          | 2023-07-29 14:29   |
| MOT test number  | 931794054721   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-08-08   |
| Advice           | Offside Rear Coil spring corroded (5.3.1 (b) (i))  |
| Advice           | Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))  |
| Advice           | Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |
| Advice           | Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) |
| Advice           | Nearside Rear Coil spring corroded (5.3.1 (b) (i))   |
| Advice           | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))   |
| Advice           | Offside Front Lower bumper and fog light damaged   |
| Advice           | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))   |
| Advice           | Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))  |

**MOT #15**

2023-07-29 14:29

**MOT test number**

574364414879

**Result**

✗ Failed

- Advice** Offside Front Lower bumper and fog light damaged
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #14**

2022-07-28 15:01

**MOT test number**

630484749535

**Result**

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2021-08-09 13:47

**MOT test number**

600592494902

**Result**

✓ Passed

- Advice** Rear Coil spring corroded n/s & o/s (5.3.1 (b) (i))

**MOT #12** 2021-08-09 13:47**MOT test number** 380178571701**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Rear Coil spring corroded n/s & o/s (5.3.1 (b) (i))**MOT #11** 2020-11-12 09:17**MOT test number** 764534994434**Result** ✓ Passed**MOT #10** 2019-06-07 08:35**MOT test number** 599827188391**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Outer Tyre slightly damaged/cracking or perishing both side (size 185.65.R 15) (5.2.3 (d) (ii))**Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Silencer & exhaust pipe system rusty.

**MOT #9** 2019-05-21 13:26**MOT test number** 344897941256**Result** ✗ Failed**DANGEROUS** Rear Brakes imbalanced across an axle by more than 50% Axle 2 (1.2.1 (b) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** The silencer exhaust rusty.**DANGEROUS** Offside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Outer Tyre slightly damaged/cracking or perishing both side (size 185.65.R 15) (5.2.3 (d) (ii))**MOT #8** 2018-06-01 14:36**MOT test number** 410509158177**Result** ✓ Passed**Advice** Phone/sat nav holder**MOT #7** 2018-06-01 09:04**MOT test number** 508008356010**Result** ✗ Failed**Advice** Phone/sat nav holder**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #6** 2017-06-10 09:22**MOT test number** 282573523900**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin and discs excess corroded (3.5.1g)

**MOT #5** 2017-06-10 08:09**MOT test number** 604015246136**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin and discs excess corroded (3.5.1g)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #4** 2016-07-02 09:27**MOT test number** 196324807383**Result** ✓ Passed**MOT #3** 2015-07-04 10:35**MOT test number** 217705285470**Result** ✓ Passed**MOT #2** 2014-07-04 09:56**MOT test number** 239335784185**Result** ✓ Passed**Notice** Rear exhaust silencer outer casing corroded and loose**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/r tyre 3mm**MOT #1** 2013-07-16 10:35**MOT test number** 649477793134**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
8 August 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 September         |
| <b>Days left</b>        | 124                             |
| <b>MOT expiry date</b>  | 8 August 2024                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

|          |  |
|----------|--|
| Damage 1 |  |
| Date     |  |
| Category |  |
| Type     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 10,000 |
| Auction value               | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FIAT had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2010-07-21               |
| Last registration          | 2023-07-29               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-07-21 | 28 mi     |
| Registration #2  | 2013-07-16 | 30.608 mi |
| Registration #3  | 2014-07-04 | 37.330 mi |
| Registration #4  | 2015-07-04 | 41.035 mi |
| Registration #5  | 2016-07-02 | 43.825 mi |
| Registration #6  | 2017-06-10 | 47.412 mi |
| Registration #7  | 2017-06-10 | 47.412 mi |
| Registration #8  | 2018-06-01 | 50.947 mi |
| Registration #9  | 2018-06-01 | 50.947 mi |
| Registration #10 | 2019-06-01 | 55.000 mi |
| Registration #11 | 2019-06-01 | 55.000 mi |
| Registration #12 | 2019-06-01 | 55.000 mi |
| Registration #13 | 2019-06-01 | 55.000 mi |
| Registration #14 | 2019-06-01 | 55.000 mi |
| Registration #15 | 2019-06-01 | 55.000 mi |
| Registration #16 | 2019-06-01 | 55.000 mi |
| Registration #17 | 2019-06-01 | 55.000 mi |
| Registration #18 | 2019-06-01 | 55.000 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1687 mm |
| Height              | 1490 mm |
| Length              | 4065 mm |
| Wheel base          | 2510 mm |
| Kerb weight         | 1040 kg |
| Max. allowed weight | 1600 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | 5839116 |