




report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO 16V VTR PLUS GRAND PICASSO
Colour	White
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2022-06-12
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-01-21
Pictures	10
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-12
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	17
Total items failed	9

MOT #17	2023-06-29 15:12
MOT test number	754493587938
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt

MOT #16	2023-06-29 08:30
MOT test number	228144300705
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Hydraulic brake calliper inadequately mounted and braking performance affected lower bolt missing (1.1.16 (c) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm 215/55/16 (5.2.3 (e))

**MOT #15** 2022-07-13 15:15**MOT test number** 367194077556**Result** ✓ Passed**MOT #14** 2022-01-31 16:04**MOT test number** 592825092677**Result** ✓ Passed**MOT #13** 2022-01-31 16:04**MOT test number** 555088454257**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2021-02-13 10:21**MOT test number** 978908769812**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11** 2021-02-13 09:56**MOT test number** 801501750166**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #10** 2020-01-21 11:45**MOT test number** 262238776652**Result** ✓ Passed

**MOT #9** 2020-01-21 09:56**MOT test number** 466700287233**Result** ✗ Failed**Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))**Advice** Fuel flap not always working**MOT #8** 2019-01-18 16:22**MOT test number** 763545881531**Result** ✓ Passed**Advice** Engine covers and under shields fitted covering some items**Advice** Front Items removed from driver's view prior to test**MOT #7** 2019-01-18 16:22**MOT test number** 106984927664**Result** ✗ Failed**Advice** Front Items removed from driver's view prior to test**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Engine covers and under shields fitted covering some items**MOT #6** 2018-01-25 11:26**MOT test number** 355932609521**Result** ✓ Passed**MOT #5** 2018-01-25 10:26**MOT test number** 625535591766**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #4** 2017-01-25 15:32**MOT test number** 664815000219**Result** ✓ Passed**MOT #3** 2016-01-28 11:41**MOT test number** 708226065385**Result** ✓ Passed**Advice** Engine covers and under shields fitted obscuring some components**MOT #2** 2015-01-21 10:29**MOT test number** 887961425095**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-01-21 10:59**MOT test number** 105911224032**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
12 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	VE60ZJJ
Plate since	2024-03-28
Current registration	VE60ZJJ
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-02-07
Last registration	2023-06-29
Complete history	See info



Registration #1	2011-02-07	29 mi
Registration #2	2014-01-21	12.385 mi
Registration #3	2015-01-21	13.353 mi
Registration #4	2016-01-28	15.937 mi
Registration #5	2017-01-25	18.695 mi
Registration #6	2018-01-25	21.151 mi
Registration #7	2018-01-25	21.151 mi
Registration #8	2019-01-18	22.427 mi
Registration #9	2019-01-18	22.427 mi
Registration #10	2020-01-21	23.621 mi
Registration #11	2020-01-21	23.621 mi
Registration #12	2020-01-21	23.621 mi
Registration #13	2020-01-21	23.621 mi
Registration #14	2020-01-21	23.621 mi
Registration #15	2020-01-21	23.621 mi
Registration #16	2020-01-21	23.621 mi
Registration #17	2020-01-21	23.621 mi
Registration #18	2020-01-21	23.621 mi
Registration #19	2020-01-21	23.621 mi
Registration #20	2020-01-21	23.621 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1486 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	FHCH1213365