



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D5 SE LUX V50
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-08
Pictures	27
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-09
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	35
Total items failed	11

MOT #18	2023-06-10 10:59
MOT test number	888579132717
Result	✓ Passed
Next expiry date	2024-06-09

MOT #17	2023-03-16 16:56
MOT test number	155528327130
Result	✗ Failed
Advice	Handbrake has little reserve travel
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Sun strip fitted not obscuring drivers view
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #16	2022-03-07 16:39
MOT test number	622697001409
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #15**

2022-03-07 11:16

**MOT test number**

501129197333

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #14**

2021-08-31 14:20

**MOT test number**

286058136236

**Result****✓ Passed****MOT #13**

2021-03-23 16:27

**MOT test number**

830749845138

**Result****✓ Passed**

- Advice** Offside Front Power steering ram has slight seepage from a joint (2.1.5 (a))
- Advice** Both rear tyres worn on inner edges

**MOT #12**

2021-03-22 16:13

**MOT test number**

768306240183

**Result****✗ Failed**

- Advice** Both rear tyres worn on inner edges
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Power steering ram has slight seepage from a joint (2.1.5 (a))

**MOT #11**

2020-02-05 11:15

**MOT test number**

876804636088

**Result****✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Both front tyres worn slightly on inner edges
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear outer brake pad slightly worn
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** O/s rear tyre worn slightly stepped on inner edges

**MOT #10** 2020-02-05 11:15**MOT test number** 539269250654**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** O/s rear tyre worn slightly stepped on inner edges**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Both front tyres worn slightly on inner edges**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear outer brake pad slightly worn**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #9** 2019-02-11 11:00**MOT test number** 965928212349**Result** ✓ Passed**MOT #8** 2018-02-13 09:24**MOT test number** 163376706979**Result** ✓ Passed**MOT #7** 2017-02-13 09:24**MOT test number** 671555578832**Result** ✓ Passed**Advice** Front brake pads will need replacing in the near future**Advice** Nearside Rear Inner tyre slightly worn on inner edges

**MOT #6** 2016-01-06 10:59**MOT test number** 608414582602**Result** ✓ Passed**Advice** FRONT BRAKE PADS WILL NEED REPLACING IN THE NEAR FUTURE**Advice** Offside Front TRYRE VERY SLIGHTLY WORN ON INNER EDGE**MOT #5** 2015-01-07 09:38**MOT test number** 965977705085**Result** ✓ Passed**MOT #4** 2013-12-13 08:59**MOT test number** 256627343394**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-12-12 09:39**MOT test number** 775626443387**Result** ✗ Failed**Fail** Fuel system component insecure (7.2.1)**Notice** Off side rear upper sidelight inop.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2013-01-03 15:14**MOT test number** 408973003006**Result** ✓ Passed



MOT #1	2011-12-13 09:36
MOT test number	188236541310
Result	✓ Passed





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>AK58FHV</b>
Plate since	2019-09-28
Current registration	<b>AK58FHV</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-01-07
Last registration	2023-06-10
Complete history	<a href="#">See info</a>



Registration #1	2009-01-07	16 mi
Registration #2	2011-12-13	27.927 mi
Registration #3	2013-01-03	35.561 mi
Registration #4	2013-12-12	42.260 mi
Registration #5	2013-12-13	44.260 mi
Registration #6	2015-01-07	51.157 mi
Registration #7	2016-01-06	58.678 mi
Registration #8	2017-02-13	67.593 mi
Registration #9	2018-02-13	80.598 mi
Registration #10	2019-02-11	91.552 mi
Registration #11	2019-05-20	95.552 mi
Registration #12	2019-05-20	95.552 mi
Registration #13	2019-05-20	95.552 mi
Registration #14	2019-05-20	95.552 mi
Registration #15	2019-05-20	95.552 mi
Registration #16	2019-05-20	95.552 mi
Registration #17	2019-05-20	95.552 mi
Registration #18	2019-05-20	95.552 mi
Registration #19	2019-05-20	95.552 mi
Registration #20	2019-05-20	95.552 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1555 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	689275