



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA S TDI
Colour	Silver
Year of manufacture	2007
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-27
Pictures	41
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-26
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	21
Total items failed	3

MOT #18 2023-08-07 12:23

MOT test number 534169723596

Result ✓ Passed

Next expiry date 2024-08-26

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #17 2022-08-27 11:58

MOT test number 569570274768

Result ✓ Passed

MOT #16 2022-03-03 10:29

MOT test number 201709529285

Result ✓ Passed**Minor** Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Minor** Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

**MOT #15** 2021-10-26 15:52**MOT test number** 113343458790**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively both side (1.1.14 (a) (i))**Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))**MOT #14** 2020-10-24 10:16**MOT test number** 526949482957**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2019-11-06 12:55**MOT test number** 587135647167**Result** ✓ Passed**MOT #12** 2018-11-07 15:06**MOT test number** 603309035456**Result** ✓ Passed**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #11** 2017-11-07 10:23**MOT test number** 859631006507**Result** ✓ Passed**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

**MOT #10** 2016-11-03 10:46**MOT test number** 204184801693**Result** ✓ Passed**MOT #9** 2015-11-06 10:39**MOT test number** 550248083018**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 205/55/16 (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 205/55/16 (4.1.E.1)**MOT #8** 2014-11-05 12:04**MOT test number** 666019004358**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2013-11-08 11:13**MOT test number** 897272913323**Result** ✓ Passed**MOT #6** 2012-11-05 15:55**MOT test number** 445150312317**Result** ✓ Passed

**MOT #5** 2012-11-05 11:11**MOT test number** 995410712385**Result** ✗ Failed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-10-12 16:12**MOT test number** 417805481219**Result** ✓ Passed**MOT #3** 2011-10-12 16:12**MOT test number** 388915281414**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #2** 2010-11-09 14:03**MOT test number** 953953610366**Result** ✓ Passed**MOT #1** 2010-01-29 12:43**MOT test number** 442949520007**Result** ✓ Passed**Notice** Both front tyres low on tread plus uneven wear but still 3/4 tread patten advise fit two new tyres soon plus wheel tracking check



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 August 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	26 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VN07LHG
Plate since	2019-09-29
Current registration	 VN07LHG
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-04-16
Last registration	2023-08-07
Complete history	See info



Registration #1	2007-04-16	28 mi
Registration #2	2010-01-29	25.273 mi
Registration #3	2010-11-09	33.763 mi
Registration #4	2011-10-12	41.893 mi
Registration #5	2012-11-05	46.804 mi
Registration #6	2012-11-05	46.804 mi
Registration #7	2013-11-08	51.332 mi
Registration #8	2014-11-05	56.223 mi
Registration #9	2015-11-06	59.644 mi
Registration #10	2016-11-03	62.504 mi
Registration #11	2016-11-03	62.504 mi
Registration #12	2016-11-03	62.504 mi
Registration #13	2016-11-03	62.504 mi
Registration #14	2016-11-03	62.504 mi
Registration #15	2016-11-03	62.504 mi
Registration #16	2016-11-03	62.504 mi
Registration #17	2016-11-03	62.504 mi
Registration #18	2016-11-03	62.504 mi
Registration #19	2016-11-03	62.504 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1508 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BXE 072319