



report date: 2024-03-29

General information

Make	NISSAN
Model	350 Z V6
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	5.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.5 mpg
Consumption extra urban	32.5 mpg
Consumption combined	24.8 mpg
CO2 emission	273 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-15
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-20
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	34
Total items failed	8

MOT #21 2024-04-18 10:55

MOT test number 480456408645

Result ✓ Passed

Next expiry date 2025-04-20

Advice Rear Tyre worn close to legal limit/worn on edge both inner shoulders (5.2.3 (e))

Advice Front Tyre slightly damaged/cracking or perishing both inner sidewalls (5.2.3 (d) (ii))

MOT #20 2023-04-20 14:35

MOT test number 433593746019

Result ✓ Passed

MOT #19 2023-04-19 12:59

MOT test number 343966657564

Result ✗ Failed

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail Windscreen washer not working (3.5 (a))

**MOT #18**

2022-04-21 15:15

MOT test number

435216485213

Result

✓ Passed

Advice

Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #17

2021-03-27 11:39

MOT test number

994855943303

Result

✓ Passed

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16

2020-04-08 10:33

MOT test number

432078445230

Result

✓ Passed

Advice

Minor oil leak nearside rocker cover gasket

MOT #15

2020-04-03 10:32

MOT test number

170791611034

Result

✗ Failed

Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Minor oil leak nearside rocker cover gasket

Fail

Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

Fail

Offside Headlamp aim too low (4.1.2 (a))

Fail

Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))

Fail

Nearside Headlamp aim too low (4.1.2 (a))

**MOT #14** 2019-04-06 09:13**MOT test number** 613719965740**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view Zone A (3.2 (a) (i))**MOT #13** 2018-04-07 08:48**MOT test number** 188132415191**Result** ✓ Passed**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear coil spring corroded o/s - n/s (2.4.C.1b)**MOT #12** 2017-04-08 10:45**MOT test number** 242067078789**Result** ✓ Passed**Advice** Front Brake pads low**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #11** 2017-04-08 10:45**MOT test number** 435485773378**Result** ✗ Failed**Advice** Front Brake pads low**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #10**

2016-03-12 11:50

MOT test number

840886185567

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Exhaust system corroded**MOT #9**

2015-03-28 10:58

MOT test number

197057285022

Result

✓ Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Exhaust system corroded**MOT #8**

2014-03-29 15:02

MOT test number

606508284061

Result

✓ Passed

Notice Front brake discs poor**Notice** Slight blow from rear exhaust flange**Notice** Exhaust heat shields rusty**MOT #7**

2013-03-23 12:24

MOT test number

988302283083

Result

✓ Passed

Notice Rear tyres getting low on tread**Notice** Front exhaust section corroded**Notice** Front brake discs worn on inner surface

**MOT #6** 2012-03-10 12:24**MOT test number** 366700672012**Result** ✓ Passed

- Notice** Exhaust system rusty
- Notice** N/s rear tyre low on tread
- Notice** N/s front tyre worn unevenly on inner edge

MOT #5 2011-03-12 12:12**MOT test number** 838161971033**Result** ✓ Passed

- Notice** Surface corrosion on front brake discs
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2010-03-30 13:02**MOT test number** 291499080084**Result** ✓ Passed**MOT #3** 2009-04-09 14:34**MOT test number** 402509199094**Result** ✓ Passed

- Notice** Front brake discs rusty and slightly pitted
- Notice** Exhaust system rusty

MOT #2 2007-11-22 10:55**MOT test number** 643026427343**Result** ✓ Passed



MOT #1	2006-11-10 11:04
MOT test number	414324916451
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 April 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	20 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-11-27
Last registration	2024-04-18
Complete history	See info



Registration #1	2003-11-27	11 mi
Registration #2	2006-11-10	3.468 mi
Registration #3	2007-11-22	3.570 mi
Registration #4	2009-04-09	7.967 mi
Registration #5	2010-03-30	11.170 mi
Registration #6	2011-03-12	14.041 mi
Registration #7	2012-03-10	18.360 mi
Registration #8	2013-03-23	21.960 mi
Registration #9	2014-03-29	24.918 mi
Registration #10	2015-03-28	27.882 mi
Registration #11	2016-03-12	30.913 mi
Registration #12	2017-04-08	34.859 mi
Registration #13	2018-04-08	38.805 mi
Registration #14	2019-04-08	42.751 mi
Registration #15	2020-04-08	46.697 mi
Registration #16	2021-04-08	50.643 mi
Registration #17	2022-04-08	54.589 mi
Registration #18	2023-04-08	58.535 mi
Registration #19	2024-04-18	62.481 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1547 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	966045