





report date: 2024-03-29

General information

Make	HYUNDAI
Model	140 CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



EJ62WKA

report date: 2024-03-29

Internet history

Entry 2

Date 2021-09-07

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2021-09-05

 Pictures
 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-24
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #10		2023-11-15 10:22
MOT test	number	456525732368
Result		✓ Passed
Next expiry date 2024-11-2		2024-11-24
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2022-11-25 11:12
MOT test number	221087208930
Result	✓ Passed
MOT #8	2021-10-28 15:18
MOT test number	218667922751
Result	✓ Passed
MOT #7	2020-11-18 13:24

MOT #7	2020-11-18 13:24
MOT test number	515512213780
Result	✓ Passed

CarCheck.co.uk page 3/12



EJ62WKA

MOT #6 2020-11-17 13:52

MOT test number 583990860628

Result X Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin attention required (1.1.13 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #5 2019-10-25 13:58

MOT test number 291133495429

Result

Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2018-11-06 15:45

MOT test number 947053390659

Result

Passed

MOT #3 2017-11-06 15:18

MOT test number 476969300152

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2016-10-20 13:44

MOT test number 300641657994

Result

Passed

CarCheck.co.uk page 4/12



MOT #1 2015-11-16 11:44

MOT test number 177141295115

Result ✓ Passed

CarCheck.co.uk page 5/12





Tax & MOT check





Tax expired: 19 March 2024

Expires: 24 November 2024

Tax status	Expired at 19 March 2024
Days left	42 days too late
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-11-20
Last registration	2023-11-15
Complete history	See info



Registration #1	2012-11-20	23 mi
Registration #2	2015-11-16	29.057 mi
Registration #3	2016-10-20	35.000 mi
Registration #4	2017-11-06	41.703 mi
Registration #5	2018-11-06	46.739 mi
Registration #6	2019-10-25	50.910 mi
Registration #7	2020-11-17	52.544 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		10.000 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number D4FDCU188751