



BV09KOB

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	Silver
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

Internet history

Entry 1

Date	2021-10-15
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-05
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	64
Total items failed	8

MOT #212024-02-06 11:08

MOT test number810985091689

Result✓ Passed

Next expiry date2025-02-05

- Advice** Reverse lights not working (march 2009)
- Advice** Offside door step corroded
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive top strut mount (5.3.6 (a) (i))
- Advice** Nearside door step corroded
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive top strut mount (5.3.6 (a) (i))

**MOT #20**

2024-01-23 10:00

MOT test number

533729016114

Result**✗ Failed****MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive top strut mount (5.3.6 (a) (i))**MAJOR** Nearside Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Advice** Reverse lights not working (march 2009)**MAJOR** Offside Rear Leaf spring fractured front eye (5.3.1 (b) (i))**MAJOR** Nearside Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside door step corroded**MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive top strut mount (5.3.6 (a) (i))**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**MAJOR** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Nearside door step corroded**MOT #19**

2022-12-22 12:16

MOT test number

442469929630

Result**✓ Passed**

**MOT #18** 2022-12-20 14:00**MOT test number** 788323584998**Result** ✗ Failed

- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Front Service brake excessively fluctuating both sides (1.2.1 (e))
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both sides and lamp cover missing (4.7.1 (b) (ii))
- MAJOR** Offside Front Headlamp lens seriously defective no beam Pattern (4.1.1 (b) (ii))

MOT #17 2021-11-15 13:09**MOT test number** 275767384829**Result** ✓ Passed**MOT #16** 2021-11-15 08:39**MOT test number** 374194336842**Result** ✗ Failed

- MAJOR** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))
- DANGEROUS** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
- MAJOR** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #15 2020-12-04 12:21**MOT test number** 712501690401**Result** ✓ Passed

- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))



MOT #14		2020-12-03 11:08
MOT test number		643384703141
Result		✗ Failed
MAJOR	Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))	
MAJOR	Headlamp aim not tested (4.1.2 (b))	
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))	
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Offside Registration plate lamp likely to become detached (4.7.1 (c) (ii))	
DANGEROUS	Nearside Rear Leaf spring main leaf fractured (5.3.1 (b) (ii))	
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))	

MOT #13		2019-12-05 16:00
MOT test number		977270585350
Result		✓ Passed

MOT #12		2019-12-03 10:35
MOT test number		989909179025
Result		✗ Failed
DANGEROUS	Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
MAJOR	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
DANGEROUS	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
MAJOR	Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))	

**MOT #11** 2018-11-28 15:42**MOT test number** 991475080605**Result** ✓ Passed**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MOT #10** 2017-11-30 16:29**MOT test number** 480032895490**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #9** 2017-11-30 16:29**MOT test number** 977250159209**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2016-06-08 11:12**MOT test number** 794641825145**Result** ✓ Passed**Advice** Oil leak**MOT #7** 2015-01-09 14:54**MOT test number** 895579205015**Result** ✓ Passed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear wheel bearing has slight play (2.6.2)

**MOT #6** 2015-01-09 11:01**MOT test number** 506959105071**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #5** 2014-02-20 13:14**MOT test number** 417441754023**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**MOT #4** 2014-02-20 09:06**MOT test number** 886591654039**Result** ✗ Failed**Fail** Offside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)

**MOT #3** 2013-02-20 10:15**MOT test number** 407431153095**Result** ✓ Passed**Notice** Service light on dash**Notice** Rear high level brake light in/op**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #2** 2012-02-20 17:15**MOT test number** 738971852020**Result** ✓ Passed**MOT #1** 2012-02-20 12:58**MOT test number** 616351152099**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Brake pad(s) wearing thin (3.5.1g)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
5 February 2025

Tax status	Valid until 1 November
-------------------	------------------------

Days left	185
------------------	-----

MOT expiry date	5 February 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-03-03
Last registration	2024-02-06
Complete history	See info



Registration #1	2009-03-03	8 mi
Registration #2	2012-02-20	43.535 mi
Registration #3	2012-02-20	43.537 mi
Registration #4	2013-02-20	56.893 mi
Registration #5	2014-02-20	69.309 mi
Registration #6	2014-02-20	69.309 mi
Registration #7	2015-01-09	79.477 mi
Registration #8	2015-01-09	79.477 mi
Registration #9	2016-06-08	104.157 mi
Registration #10	2017-11-30	126.060 mi
Registration #11	2017-11-30	126.060 mi
Registration #12	2018-11-28	130.264 mi
Registration #13	2019-05-20	151.277 mi
Registration #14	2019-05-20	151.277 mi
Registration #15	2019-05-20	151.277 mi
Registration #16	2019-05-20	151.277 mi
Registration #17	2019-05-20	151.277 mi
Registration #18	2019-05-20	151.277 mi
Registration #19	2019-05-20	151.277 mi
Registration #20	2019-05-20	151.277 mi
Registration #21	2019-05-20	151.277 mi
Registration #22	2019-05-20	151.277 mi
Registration #23	2019-05-20	151.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	9R16420