



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | PIXO N-TEC |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 96 mph |
| 0 - 60 mph | 14.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 67 BHP |
| Max. torque | 90 Nm at 3.400 rpm |
| Engine capacity | 996 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 103 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-09 |
| Pictures | 6 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2021-09-30 |
| MOT pass rate | 60 % |
| MOT passed | 9 |
| Failed MOT tests | 6 |
| Total advice items | 33 |
| Total items failed | 18 |

MOT #152020-09-11 12:40

MOT test number281689988951

Result✓ Passed

Next expiry date2021-09-30

- AdviceOffside Play in steering rack inner joint(s)
- AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2020-09-10 09:20

MOT test number

449010946586

Result**✗ Failed**

- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #13

2019-09-23 14:54

MOT test number

387083025088

Result**✓ Passed**

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #12**

2019-09-23 08:46

MOT test number

667908354675

Result

✗ Failed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Windscreen washer not working (3.5 (a))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11**

2018-09-11 15:06

MOT test number

853199338517

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #10**

2018-09-11 09:40

MOT test number

803916915417

Result

✗ Failed

Fail Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #9** 2017-09-11 12:49**MOT test number** 439190190037**Result** ✓ Passed

Advice Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #8 2017-09-11 12:49**MOT test number** 398471268097**Result** ✗ Failed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Pass with rectification Offside Stop lamp not working (1.2.1b)

MOT #7 2016-09-24 09:57**MOT test number** 845358570531**Result** ✓ Passed**MOT #6** 2016-09-24 09:57**MOT test number** 675530682923**Result** ✗ Failed

Pass with rectification Registration plate lamp not working (1.1.C.1d)



| | |
|------------------------|---|
| MOT #5 | 2015-09-19 09:25 |
| MOT test number | 335777061856 |
| Result | ✓ Passed |
| Advice | Offside Front Brake pipe slightly corroded (3.6.B.2c) |
| Advice | Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a) |

| | |
|--------------------------------|---|
| MOT #4 | 2015-09-19 09:25 |
| MOT test number | 146608146583 |
| Result | ✗ Failed |
| Pass with rectification | Offside Front position lamp(s) not working (1.1.A.3b) |
| Advice | Offside Front Brake pipe slightly corroded (3.6.B.2c) |
| Pass with rectification | Offside Registration plate lamp not working (1.1.C.1d) |
| Advice | Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a) |

| | |
|------------------------|------------------|
| MOT #3 | 2014-09-11 12:32 |
| MOT test number | 826634854286 |
| Result | ✓ Passed |

| | |
|------------------------|-----------------------------|
| MOT #2 | 2013-09-21 10:03 |
| MOT test number | 857544463215 |
| Result | ✓ Passed |
| Notice | Cut on tread o/s/front tyre |

| | |
|------------------------|--|
| MOT #1 | 2012-09-22 09:36 |
| MOT test number | 967616362220 |
| Result | ✓ Passed |
| Notice | Oil leak |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✕
Untaxed

Tax expired:
16 June 2021

✕
MOT

Expired:
30 September 2021

| | |
|------------------|---------------------------------|
| Tax status | Expired at 16 June 2021 |
| Days left | 1049 days too late |
| MOT expiry date | 30 September 2021 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | FY59HXF |
| Plate since | 2019-09-29 |
| Current registration | FY59HXF |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-09-30 |
| Last registration | 2020-09-11 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-09-30 | 17 mi |
| Registration #2 | 2012-09-22 | 70.320 mi |
| Registration #3 | 2013-09-21 | 96.432 mi |
| Registration #4 | 2014-09-11 | 120.226 mi |
| Registration #5 | 2015-09-19 | 146.919 mi |
| Registration #6 | 2015-09-19 | 146.919 mi |
| Registration #7 | 2016-09-24 | 170.207 mi |
| Registration #8 | 2016-09-24 | 170.207 mi |
| Registration #9 | 2017-09-11 | 183.743 mi |
| Registration #10 | 2018-09-20 | 201.277 mi |
| Registration #11 | 2019-09-20 | 221.277 mi |
| Registration #12 | 2020-09-20 | 241.277 mi |
| Registration #13 | 2021-09-20 | 261.277 mi |
| Registration #14 | 2022-09-20 | 281.277 mi |
| Registration #15 | 2023-09-20 | 301.277 mi |
| Registration #16 | 2024-09-20 | 321.277 mi |
| Registration #17 | 2025-09-20 | 341.277 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1630 mm |
| Height | 1470 mm |
| Length | 3565 mm |
| Wheel base | 2360 mm |
| Kerb weight | 855 kg |
| Max. allowed weight | 1250 kg |

Additional information

| | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 107462 |