



report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | KIA |
| Model | RIO CRDI 2 ECODYNAMICS |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 98 mph |
| 0 - 60 mph | 15.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 74 BHP |
| Max. torque | 170 Nm at 1.500 rpm |
| Engine capacity | 1.120 cc |
| Cylinders | 3 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-12 |
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 29 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #12 | 2024-03-13 09:40 |
| MOT test number | 834836164731 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-12 |
| Advice | Rear General underbody corrosion |
| Advice | Front Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #11 | 2024-03-09 10:43 |
| MOT test number | 734818978801 |
| Result | ✗ Failed |
| Advice | Front Oil leak, but not excessive (8.4.1 (a) (i)) |
| DANGEROUS | Rear Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii)) |
| MAJOR | Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice | Rear General underbody corrosion |
| DANGEROUS | Rear Inner Brake disc in such a condition that it is seriously weakened both sides (1.1.14 (a) (ii)) |

**MOT #10** 2023-02-23 13:00**MOT test number** 228489403703**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front +rear (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge plus has nail (5.2.3 (e))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2023-02-23 11:22**MOT test number** 431775653382**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front +rear (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge plus has nail (5.2.3 (e))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #8 2022-02-16 13:14**MOT test number** 498622621802**Result** ✓ Passed

- Minor** Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #7** 2022-02-15 15:21**MOT test number** 182926095172**Result** ✗ Failed**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #6** 2021-02-16 11:24**MOT test number** 666217365422**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust corroding**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2020-01-28 11:23**MOT test number** 823674474575**Result** ✓ Passed**MOT #4** 2019-02-05 11:02**MOT test number** 622713894556**Result** ✓ Passed**MOT #3** 2018-02-05 14:35**MOT test number** 710655746843**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #2 | 2018-02-05 11:17 |
| MOT test number | 953762027337 |
| Result | ✗ Failed |
| Fail | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Fail | Nearside Registration plate lamp not working (1.1.C.1d) |

| | |
|-----------------|------------------|
| MOT #1 | 2017-01-12 09:46 |
| MOT test number | 356076419647 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
12 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 12 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------|
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |

More info >

Plate changes

See in this check if this KIA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YE63LBJ |
| Plate since | 2019-09-28 |
| Current registration | YE63LBJ |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2014-02-11 |
| Last registration | 2024-03-13 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2014-02-11 | 24 mi |
| Registration #2 | 2017-01-12 | 56.722 mi |
| Registration #3 | 2018-02-05 | 66.682 mi |
| Registration #4 | 2018-02-05 | 66.682 mi |
| Registration #5 | 2019-02-05 | 75.895 mi |
| Registration #6 | 2020-01-28 | 87.817 mi |
| Registration #7 | 2021-02-16 | 95.754 mi |
| Registration #8 | 2022-03-20 | 101.277 mi |
| Registration #9 | 2022-03-20 | 101.277 mi |
| Registration #10 | 2022-03-20 | 101.277 mi |
| Registration #11 | 2022-03-20 | 101.277 mi |
| Registration #12 | 2022-03-20 | 101.277 mi |
| Registration #13 | 2024-03-13 | 101.277 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 92% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1720 mm |
| Height | 1455 mm |
| Length | 4045 mm |
| Wheel base | 2570 mm |
| Kerb weight | 1293 kg |
| Max. allowed weight | 1640 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 43 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|--------------|
| Number of axles | 2 |
| Engine number | D3FADH323351 |