



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Grey
Year of manufacture	2014
Top speed	140 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	60.1 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 3

Date	2023-04-28
Pictures	38
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2

Date	2022-11-14
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2022-06-02
Pictures	45
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #9	2023-06-30 09:42
MOT test number	264854939763
Result	✓ Passed
Next expiry date	2024-06-29

MOT #8	2022-06-07 08:57
MOT test number	382711848343
Result	✓ Passed

MOT #7	2021-12-03 14:49
MOT test number	155143793183
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2021-12-02 12:50**MOT test number** 849423832034**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2020-12-03 11:18**MOT test number** 640769089696**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2019-12-05 12:42**MOT test number** 993137417901**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2018-12-05 15:47**MOT test number** 335764507950**Result** ✓ Passed



MOT #2	2018-12-05 11:30
MOT test number	409667370644
Result	✗ Failed
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm 225/50 17 primacy (5.2.3 (e))	

MOT #1	2017-12-07 12:25
MOT test number	505239969174
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

X

Untaxed

Tax expired:
31 May 2022

✓

MOT

Expires:
29 June 2024

Tax status	Expired at 31 May 2022
Days left	699 days too late
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-11-03
Last registration	2023-06-30
Complete history	See info



Registration #1	2014-11-03	8 mi
Registration #2	2017-12-07	17.258 mi
Registration #3	2018-12-05	21.279 mi
Registration #4	2018-12-05	21.281 mi
Registration #5	2019-12-05	24.654 mi
Registration #6	2020-12-03	26.417 mi
Registration #7	2021-12-02	28.009 mi
Registration #8	2022-06-30	29.277 mi
Registration #9	2022-06-30	29.277 mi
Registration #10	2022-06-30	29.277 mi
Registration #11	2022-06-30	29.277 mi
Registration #12	2022-06-30	29.277 mi
Registration #13	2023-06-30	29.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4854 mm
Wheel base	2835 mm
Kerb weight	1688 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1518650