





report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-02-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-03-10
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	3
Total items failed	11

MOT #11	2023-03-02 16:39
MOT test number	918538608903
Result	✓ Passed
Next expiry date	2024-03-10

MOT #10	2022-03-10 17:51
MOT test number	841201347257
Result	<b>√</b> Passed

MOT #9	2022-03-07 09:59
MOT test number	703217865999
Result	<b>×</b> Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened nears (a) (ii))	ide and offside (1.1.14

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

× Failed

MOT #8 2021-03-11 14:47

**MOT test number** 243882246942

Advice

Result

Fail

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2021-03-10 13:32

**MOT test number** 465326590945

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Nearside Brake pipe excessively corroded main at rear (1.1.11 (c))

Fail Offside Brake pipe excessively corroded main at rear (1.1.11 (c))

MOT #6 2020-02-18 15:25

**MOT test number** 612925112447

**Result** 
✓ Passed

MOT #5 2019-06-12 10:58

MOT test number 953521004098

**MOT #4** 2019-06-05 11:56

MOT test number 816713594356

Result X Failed

Fail Offside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))

Fail Offside Front Suspension arm attachment bracket/mounting insecure ball joint nut split pin missing

(5.3.3 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2018-09-19 08:46
MOT test number	688580738618
Result	✓ Passed
MOT #2	2017-10-19 09:50
MOT test number	654985792665
Result	✓ Passed
MOT #1	2016-08-24 08:51
MOT test number	193208575554
Result	✓ Passed

CarCheck.co.uk page 5/12



BX63WHR report date: 2024-03-28

Tax & MOT check



Tax expired: 31 December 2023

# **Х** МОТ

Expired:
10 March 2024

Expired at 31 December 2023

Days left 119 days too late

MOT expiry date 10 March 2024

Full MOT history See MOT history

### Tax calculation

**Tax status** 

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many ow VAUXHALL have? Check it in the premium report and see all owner registrations. Downloner.		
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this VAUXHALL had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	NK NE	
Plate since		

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-01
Last registration	2023-03-02
Complete history	See info



Registration #1	2013-09-01	10 mi
Registration #2	2016-08-24	38.688 mi
Registration #3	2017-10-19	50.109 mi
Registration #4	2018-09-19	53.503 mi
Registration #5	2019-06-05	58.445 mi
Registration #6	2019-06-12	58.448 mi
Registration #7	2020-02-18	63.425 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 46
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ

CarCheck.co.uk page 12/12