



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T SE S60
Colour	Yellow
Year of manufacture	2003
Top speed	140 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	177 BHP
Max. torque	240 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.7 mpg
CO2 emission	215 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-08-28
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-12-22
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	10
Total items failed	15

MOT #21	2021-12-23 14:28
MOT test number	854968714981
Result	✓ Passed
Next expiry date	2022-12-22

MOT #20	2021-12-14 12:33
MOT test number	581369824066
Result	✗ Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Rear Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))

MOT #19	2020-11-20 16:08
MOT test number	858477080430
Result	✓ Passed

**MOT #18** 2019-05-14 08:59**MOT test number** 243019384334**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #17** 2018-05-05 08:09**MOT test number** 776239520650**Result** ✓ Passed**MOT #16** 2016-11-24 10:18**MOT test number** 907608700414**Result** ✓ Passed**MOT #15** 2015-12-18 10:34**MOT test number** 665338394915**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**MOT #14** 2014-12-13 10:21**MOT test number** 945247044339**Result** ✓ Passed**MOT #13** 2013-12-14 09:29**MOT test number** 475768843482**Result** ✓ Passed

**MOT #12** 2013-12-13 12:38**MOT test number** 615067843307**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #11** 2012-11-26 13:24**MOT test number** 247031432361**Result** ✓ Passed**MOT #10** 2012-11-26 13:24**MOT test number** 307221732313**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2011-12-22 12:46**MOT test number** 658446651371**Result** ✓ Passed

**MOT #8** 2011-12-22 12:46**MOT test number** 979546951364**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2010-12-21 11:40**MOT test number** 484045050383**Result** ✗ Failed**Pass with rectification** Centre Exhaust system not adequately supported (7.1.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2010-12-21 11:40**MOT test number** 442845950388**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-06-10 10:34**MOT test number** 744081169172**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-06-20 14:01**MOT test number** 583432278127**Result** ✓ Passed



MOT #3	2007-05-21 09:41
MOT test number	333361947144
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Front Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b)

MOT #2	2007-05-21 09:41
MOT test number	960101347180
Result	✓ Passed

MOT #1	2006-05-17 16:06
MOT test number	380857036163
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-05-29
Last registration	2021-12-23
Complete history	See info



Registration #1	2003-05-29	18 mi
Registration #2	2006-05-17	13.274 mi
Registration #3	2007-05-21	17.700 mi
Registration #4	2008-06-20	20.476 mi
Registration #5	2009-06-10	29.294 mi
Registration #6	2010-12-21	45.579 mi
Registration #7	2011-12-22	59.399 mi
Registration #8	2012-11-26	74.273 mi
Registration #9	2013-12-13	88.307 mi
Registration #10	2013-12-14	88.307 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1813 mm
Height	1428 mm
Length	4603 mm
Wheel base	2715 mm
Kerb weight	1492 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	2759948